

0004



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

PH

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Records
Partial: Complete: XXX Exploration:
Inspection Date & Time: 11/4/99 / 8:30a.m.-11:30a.m.
Date of Last Inspection: 11/1/99

Mine Name: Cottonwood/Wilberg Mine County: Emery Permit Number: ACT/015/019
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Chuck Semborski
State Officials(s): Bill Malencik Federal Official(s): None
Weather Conditions: Sunny, Warm, 60's
Existing Acreage: Permitted- 11508 Disturbed- 102 Regraded- Seeded- Bonded- 102
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June)_____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 11/4/99

(Comments are Numbered to Correspond with Topics Listed Above)

SUMMARY

-No violations were issued as a result of the instant inspection.

-The amendment on the 4,000 acres permit relinquishment is still pending. Two unfinished items include water issues on and adjoining Cottonwood Springs; bonding--surety bond and liability insurance on the areas. On the Cottonwood Spring matter, the coal program manager wrote Janette Kaiser, USFS, a decision letter. This letter is intended to close this case on the Cottonwood Spring issues.

-Phase I Bond Release application is in the process of final review for a portion of the reclaimed Cottonwood waste rock site. It is pending a review and approval by OSM.

-PacifiCorp is making preliminary plans to relinquish part of the undisturbed area. The area is needed by Texaco.

-Miller Canyon seals and PacifiCorp Bond Release. A field trip was organized by PacifiCorp to Miller Canyon. Personnel invited to attend included: BLM, USFS, and DOGM. Those in attendance included: Chuck Semborski, Dennis Oakley, Jeff Defreest, and Bill Malencik. The field trip was completed on 11/1/99.

Facts: The three portals are located in a steep walk-in canyon and contains a total of 0.02 acres. The site is outside the designed disturbed area as identified in the MRP. The area was reclaimed and seeded in the summer of 1999.

The area reclamation is successful as observed by all participants. The Division has before it a phase III bond release. The understanding the permittee has with DEQ is that the UPDES permit will be considered as a separate action by DEQ. The small area reclaimed has been successful as noted above.

The USFS representative and the undersigned recommend the phase III bond release by approved.

4B. **HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS**

There are five sediment ponds. Two at the Cottonwood/Wilberg mine, MSHA ponds, and commonly referred to as the north and south impoundments.

There are two small sediment ponds at the Cottonwood Fan Portal. These are incised sediment ponds. The permittee is working with Sharon Falvey on reclaiming the two sediment ponds.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/019

DATE OF INSPECTION: 11/4/99

(Comments are Numbered to Correspond with Topics Listed Above)

One sediment pond collects runoff from the active waste rock site.

All impoundments are designed and details included in the MRP on the north and south impoundments. MSHA made a determination as follows:

- (1) The capacity of both ponds are such that MSHA approval was granted.
- (2) Both ponds would be inspected monthly and a variance was granted.
- (3) Both ponds would not require an open channel spillway per OSM granted variance.

The company submitted all the required reports.

4E. **HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS**

Reports for the last monthly period were submitted to responsible agencies. The Cottonwood Mine was discharging mine water.

7. **COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS**

Coal mine waste is stored west of State Highway 57 on federal land. The permittee has a ROW grant from BLM. Waste rock site services the Cottonwood/Wilberg, Trail Mountain, and Des Bee Dove mines. See comment on page 2 on a deletion of 12.02 acres of undisturbed DOGM permitted area. The quarterly reports were submitted for the third quarter.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Chuck Semborski (PacifiCorp) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM) Filed to: Price Field Office
Date: November 24, 1999

Inspector's Signature:  #26
Wm. J. Malencik