



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

Handwritten initials/signature

Partial: XXX Complete: Exploration:
Inspection Date & Time: 08/21/2001 / 2:00pm-4:00pm
Date of Last Inspection: 07/23/2001

Mine Name: Cottonwood/Wilberg Mine County: Emery Permit Number: C/015/019
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Dennis Oakley
State Official(s): Stephen J. Demczak, Karl Housekeeper Federal Official(s): None
Weather Conditions: Warm, 80's
Existing Acreage: Permitted 11508 Disturbed 102 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/019

DATE OF INSPECTION: 8/21/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4A. HYDROLOGIC BALANCE: DIVERSIONS

Several diversions were spot-checked throughout the property. All ditches were functional and complied with the R645 Coal Rules. A couple of the ditches did have some rocks within the diversion but water flow would not be hindered.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were inspected with no hazardous conditions being noticed. The sediment ponds did contain water but will not likely discharge in the near future.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The road side silt fences for topsoil protection were functioning as designed. There were no signs of wind or water erosion.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The water monitoring for first quarter was submitted to the Division using the Electronic Data System. The second quarter information is being compiled by the permittee and will be submitted to the Division by the end of the third quarter. The permittee is in the process of taking the third quarter water samples and will be finished by the end of the third quarter. The inspector used the EDS system prior to inspection.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile was inspected with no signs of hazardous conditions being noticed. Several piles of refuse were stacked close together on the top lift. The permittee will level and compact the refuse pile and remove non-coal waste material.

8. NONCOAL WASTE

The mine property was clear of non-coal waste material.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/019

DATE OF INSPECTION: 8/21/2001

15. CESSATION OF OPERATIONS

The mine has applied for Temporary Cessation of Operations. This amendment is being reviewed by the Division.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new facilities were constructed.

Inspector's Signature: _____


Stephen J. Demczak #39

Date: August 23, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office

O:\015019.CWW\Compliance\2001\p_0821.wpd