

012  
Uncoming  
C/015/019

**From:** "Oakley, Dennis" <dennis.oakley@pacificcorp.com>  
**To:** "Pam Grubaugh-Littig" <pamgrubaughlittig@utah.gov>  
**Date:** 11/5/02 2:05PM  
**Subject:** Issues Involving C/015/019-AM01C

Pam,

This letter is in response to our phone conversation on 10/30/02 regarding clean copy submittals of AM01C. This amendment originated in October, 2001 to remove redundant sediment control structures at the Cottonwood Fan Portal area. Map 3-13 of Volume 11 in the Cottonwood/Wilberg MRP was modified to remove silt fences along ditch DD-4 and two of the three silt fences along the county road. In addition, the mine discharge weir and valve assembly was also incorporated on this map.

During the same time period, Phase I bond release for the Cottonwood Fan Portal area (BR00D-3) was in progress. Map 3-13 was also modified in this amendment. I talked to a Division representative (sorry I can't remember who I talked to) about using Map 3-13 from BR00D-3 to satisfy the clean copies of AM01C since the maps were identical. the representative agreed that this would be best. Unfortunately, I failed to follow this action up with a letter and the process for AM01C set idled.

Please accept this letter for an explanation to complete and close AM01C. We have an incorporated stamp on Map 3-13 for January 3, 2002. Sorry for any inconvenience, but hopefully we can put this issue to rest.

Sincerely,

Dennis Oakley  
Environmental Engineer  
  
Energy West Mining Company  
15 North Main Street  
Huntington, Utah 84528  
Phone: 435.687.4825  
Fax: 435.687.2695  
E-mail: dennis.oakley@pacificcorp.com

-----  
This email is confidential and may be legally privileged.

It is intended solely for the addressee. Access to this email by anyone else, unless expressly approved by the sender or an authorized addressee, is unauthorized.

If you are not the intended recipient, any disclosure, copying, distribution or any action omitted or taken in reliance on it, is prohibited and may be unlawful. If you believe that you have received this email in error, please contact the sender, delete this e-mail and destroy all copies.

=====

Pam,

This letter is in response to our phone conversation on 10/30/02 regarding clean copy submittals of AM01C. This amendment originated in October, 2001 to remove redundant sediment control structures at the Cottonwood Fan Portal area. Map 3-13 of Volume 11 in the Cottonwood/Wilberg MRP was modified to remove silt fences along ditch DD-4 and two of the three silt fences along the county road. In addition, the mine discharge weir and valve assembly was also incorporated on this map.

During the same time period, Phase I bond release for the Cottonwood Fan Portal area (BR00D-3) was in progress. Map 3-13 was also modified in this amendment. I talked to a Division representative (sorry I can't remember who I talked to) about using Map 3-13 from BR00D-3 to satisfy the clean copies of AM01C since the maps were identical. The representative agreed that this would be best. Unfortunately, I failed to follow this action up with a letter and the process for AM01C set idled.

Please accept this letter for an explanation to complete and close AM01C. We have an incorporated stamp on Map 3-13 for January 3, 2002. Sorry for any inconvenience, but hopefully we can put this issue to rest.

Sincerely,

*Dennis Oakley*  
*Environmental Engineer*

*Energy West Mining Company*  
*15 North Main Street*  
*Huntington, Utah 84528*  
*Phone: 435.687.4825*  
*Fax: 435.687.2695*  
*E-mail: [dennis.oakley@pacificorp.com](mailto:dennis.oakley@pacificorp.com)*

---

This email is confidential and may be legally privileged.

It is intended solely for the addressee. Access to this email by anyone else, unless expressly approved by the sender or an authorized addressee, is unauthorized.

If you are not the intended recipient, any disclosure, copying, distribution or any action omitted or taken in reliance on it, is prohibited and may be unlawful. If you believe that you have received this email in error, please contact the sender, delete this e-mail and destroy all copies.

---

---

Received: from service2.pacificorp.com  
by gw.it.as.ex.state.ut.us; Tue, 05 Nov 2002 14:05:13 -0700  
Received: from pdxmms01.pacificorp.com (pdxmms01 [131.219.239.165])  
by service2.pacificorp.com (8.11.6+Sun/8.11.6) with ESMTP id gA5L4as04873  
for <pamgrubaughlittig@utah.gov>; Tue, 5 Nov 2002 13:04:37 -0800 (PST)  
Received: from 131.219.239.49 by pdxmms01.pacificorp.com with ESMTP (MMS  
SMTP Relay (MMS v5.0)); Tue, 05 Nov 2002 13:08:25 -0800  
X-Server-Uuid: F7E6B7FD-E7F1-4C27-B07F-40F03E9AD25E  
Received: by pdxexc01.pacificorp.com with Internet Mail Service (  
5.5.2656.59) id <VZ7Q79CY>; Tue, 5 Nov 2002 13:05:00 -0800  
Message-ID: <F3D743F24D7BD311B82000508B5513BB736B64@ewmexu01.pacificorp.com>  
From: "Oakley, Dennis" <dennis.oakley@pacificorp.com>  
To: "Pam Grubaugh-Littig" <pamgrubaughlittig@utah.gov>  
Subject: Issues Involving C/015/019-AM01C  
Date: Tue, 5 Nov 2002 13:04:57 -0800  
MIME-Version: 1.0  
X-Mailer: Internet Mail Service (5.5.2656.59)  
X-WSS-ID: 11D6ECC318362-01-01  
Content-Type: multipart/alternative;  
boundary="-----\_=\_NextPart\_001\_01C2850E.FF0D6720"

This message is in MIME format. Since your mail reader does not understand  
this format, some or all of this message may not be legible.

-----\_=\_NextPart\_001\_01C2850E.FF0D6720  
Content-Type: text/plain;  
charset=iso-8859-1  
Content-Transfer-Encoding: 7bit

Pam,

This letter is in response to our phone conversation on 10/30/02 regarding  
clean copy submittals of AM01C. This amendment originated in October, 2001  
to remove redundant sediment control structures at the Cottonwood Fan Portal  
area. Map 3-13 of Volume 11 in the Cottonwood/Wilberg MRP was modified to  
remove silt fences along ditch DD-4 and two of the three silt fences along  
the county road. In addition, the mine discharge weir and valve assembly was  
also incorporated on this map.

During the same time period, Phase I bond release for the Cottonwood Fan  
Portal area (BR00D-3) was in progress. Map 3-13 was also modified in this  
amendment. I talked to a Division representative (sorry I can't remember who  
I talked to) about using Map 3-13 from BR00D-3 to satisfy the clean copies  
of AM01C since the maps were identical. the representative agreed that this  
would be best. Unfortunately, I failed to follow this action up with a  
letter and the process for AM01C set idled.

Please accept this letter for an explanation to complete and close AM01C. We  
have an incorporated stamp on Map 3-13 for January 3, 2002. Sorry for any  
inconvenience, but hopefully we can put this issue to rest.

Sincerely,

Dennis Oakley  
Environmental Engineer

Energy West Mining Company  
15 North Main Street  
Huntington, Utah 84528  
Phone: 435.687.4825  
Fax: 435.687.2695  
E-mail: dennis.oakley@pacificorp.com

-----  
This email is confidential and may be legally privileged.

It is intended solely for the addressee. Access to this email by anyone else, unless expressly approved by the sender or an authorized addressee, is unauthorized.

If you are not the intended recipient, any disclosure, copying, distribution or any action omitted or taken in reliance on it, is prohibited and may be unlawful. If you believe that you have received this email in error, please contact the sender, delete this e-mail and destroy all copies.

=====  
-----\_=\_NextPart\_001\_01C2850E.FF0D6720

Content-Type: text/html;  
charset=iso-8859-1  
Content-Transfer-Encoding: quoted-printable

```
<!DOCTYPE HTML PUBLIC "-//W3C//DTD HTML 3.2//EN">
<HTML>
<HEAD>
<META HTTP-EQUIV="Content-Type" CONTENT="text/html;
charset=iso-8859-1">
<META NAME="Generator" CONTENT="MS Exchange Server version 5.5.2654.45">
<TITLE>Issues Involving C/015/019-AM01C</TITLE>
</HEAD>
<BODY>
```

```
<P><FONT SIZE=2 FACE="Arial">Pam,</FONT>
</P>
```

```
<P><FONT SIZE=2 FACE="Arial">This letter is in response to our phone
conversation on 10/30/02 regarding clean copy submittals of AM01C. This
amendment originated in October, 2001 to remove redundant sediment control
structures at the Cottonwood Fan Portal area. Map 3-13 of Volume 11 in the
Cottonwood/Wilberg MRP was modified to remove silt fences along ditch DD-4
and two of the three silt fences along the county road. In addition, the
mine discharge weir and valve assembly was also incorporated on this
map.</FONT></P>
```

```
<P><FONT SIZE=2 FACE="Arial">During the same time period, Phase I bond
release for the Cottonwood Fan Portal area (BR00D-3) was in progress. Map
3-13 was also modified in this amendment. I talked to a Division
representative (sorry I can't remember who I talked to) about using Map 3-1
```

from BR00D-3 to satisfy the clean copies of AM01C since the maps were identical. the representative agreed that this would be best. Unfortunately

I failed to follow this action up with a letter and the process for AM01C set idled.</FONT></P>

<P><FONT SIZE=2 FACE="Arial">Please accept this letter for an explanation to complete and close AM01C. We have an incorporated stamp on Map 3-13 for January 3, 2002. Sorry for any inconvenience, but hopefully we

can put this issue to rest.</FONT></P>

<P><FONT SIZE=2 FACE="Arial">Sincerely,</FONT>

</P>

<BR>

<P><FONT COLOR="#0000FF" SIZE=6 FACE="Coronet">Dennis Oakley</FONT>

<BR><B><I><FONT FACE="CityBlueprint">Environmental Engineer</FONT></I></B>

</P>

<P><B><I><FONT FACE="CityBlueprint">Energy West Mining

Company</FONT></I></B>

<BR><B><I><FONT FACE="CityBlueprint">15 North Main Street</FONT></I></B>

<BR><B><I><FONT FACE="CityBlueprint">Huntington, Utah 84528</FONT></I></B>

<BR><B><I><FONT SIZE=2 FACE="CityBlueprint">Phone:<FONT FACE="Courier

New"></FONT> 435.687.4825</FONT></I></B>

<BR><B><I><FONT SIZE=2 FACE="CityBlueprint">Fax:<FONT FACE="Courier

New">&nbsp;&nbsp;&nbsp;</FONT> 435.687.2695</FONT></I></B>

<BR><B><I><FONT SIZE=2 FACE="CityBlueprint">E-mail:<FONT FACE="Courie

r

New"></FONT> dennis.oakley@pacificorp.com</FONT></I></B>

</P>

</BODY>

</HTML>

<P>-----

-----<br>

<br>

<br>

This email is confidential and may be legally privileged.<br>

<br>

It is intended solely for the addressee. Access to this email by anyone else, unless expressly approved by the sender or an authorized addressee, i

s

unauthorized.<br>

<br>

If you are not the intended recipient, any disclosure, copying, distributio

n

or any action omitted or taken in reliance on it, is prohibited and may be

unlawful. If you believe that you have received this email in error, please

contact the sender, delete this e-mail and destroy all copies.<br>

<br>


<br>

=====  
=====  
=====

===<br>  
</P>

-----\_=\_NextPart\_001\_01C2850E.FF0D6720--

# Old Johnson Reclamation Project




Drafted by: PAW on 11/29/01  
 Topographic layer:  
 Mahogany Point 7.5' USGS Quad  
 Contour interval: 80 feet


400 0 400 800 1200 1600 2000 Feet

Scale 1:12,000

## Old Johnson Abandoned Mine Location Map (sites 18-20) Township 17 South, Range 6 East, Section 25 (SLBM) Emery County Group, Map Sheet 5 of 7



Utah Oil Gas and Mining  
 Abandoned Mine Reclamation Program



12/10/02