



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor
Robert L. Morgan
Executive Director
Lowell P. Braxton
Division Director

0274 OK

INSPECTION REPORT

Partial XXX Complete Exploration
Inspection Date: 10/31/2002 / Time: 1:30 to 3:00.
Date of Last Inspection: 09/19/2002

Mine Name: Cottonwood/Wilberg Mine County: Emery Permit Number: C/015/019
Permittee and/or Operator's Name: PacifiCorp
Business Address: P.O. Box 310, Huntington, Utah 84528
Company Official(s): Dennis Oakley State Official(s): Joe Helfrich
Federal Official(s): None Weather Conditions: 55, sunny, windy
Type of Mining Activity: Underground XXX Surface Prep Plant Other
Existing Acreage: Permitted 11532 Disturbed 102 Regraded Seeded
Status: Temporary Cessation

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, EXPLOSIVES, DISPOSAL OF EXCESS SPOIL, PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES, SLIDES AND OTHER DAMAGE, CONTEMPORANEOUS RECLAMATION, BACKFILLING AND GRADING, REVEGETATION, SUBSIDENCE CONTROL, CESSATION OF OPERATIONS, ROADS, OTHER TRANSPORTATION FACILITIES, SUPPORT FACILITIES/UTILITY INSTALLATIONS, AVS CHECK, AIR QUALITY PERMIT, BONDING & INSURANCE.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/019

DATE OF INSPECTION: 10/31/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. **PERMITS, CHANGE, TRANSFER, RENEWAL, SALE**

There are two amendments pending, MT02, the Cottonwood midterm review. A deficiency response was sent on 10/30/2002, due 12/03/2002 and BR00D, the Phase one bond release for the Cottonwood Fan Portal area. A deficiency response was sent on 10/22/2002, due on 01/22/03.

2. **SIGNS AND MARKERS**

Permit entry signs were in place for the Cottonwood Fan portal. Disturbed area markers were noticed.

4A. **HYDROLOGIC BALANCE: DIVERSIONS**

Additional work adjacent to the silt fence located below the Cottonwood fan portal has been completed.

13. **REVEGETATION**

Vegetation is emerging from the two catch basin reclaimed areas.

Inspector's Signature: _____

Joseph C. Helfrich
Joseph C. Helfrich #1

Date: November 1, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office

O:\015019.CWW\Compliance\2002\p_1031.doc