

0007



SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS, AND MINING

CLEON B. FEIGHT
Director

1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

July 2, 1981

0367470

REGISTERED RETURN RECEIPT REQUESTED

ACT/015/025
#4

Mr. Wendell Owen
Co-op Mining Company
P. O. Box 1245
Huntington, Utah 84528

RE: Compliance With
Stipulations

Dear Mr. Owen:

Pursuant to your letter of May 19, 1981, regarding culvert installation, riprapping and trash rack installation, at the time of the March 26, 1981 inspection, all the culverts were not complete. Specifically, the one that your lower pad will be covering. This was inspected with Dennis White and at that time the culvert installation had not been completed nor had there been an inlet structure built nor had there been a trash rack placed over it, merely because the culverting had not been done yet.

In reference to other portions of your letter dated May 19, 1981, please refer to your six stipulations agreed upon by yourself on March 12, 1980. If you are having problems meeting these stipulations or cannot comply with them, please contact the Division. If you feel these stipulations have been met, members from the Division will be more than happy to conduct an inspection of your area so that you may commence mining activities. Till then, please be advised that no mining activity occur at the Bear Creek Canyon Portal Development Area.

Sincerely,

JOSEPH C. HELFRICH
RECLAMATION SOILS SPECIALIST

JCH/btm