

0057



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

June 25, 1991

Mr. Wendell Owen
Co-Op Mining Company
P.O. Box 1245
Huntington, Utah 84528

Dear Mr. Owen:

Re: Inadequate Hydrology Maps, Co-Op Mining Company, Bear Canyon Mine,
ACT/015/025, Folder #2, Emery County, Utah

The Division commenced review of hydrology maps (Plates 7-1A, B, C, D) that were submitted due to issues outlined in the Division Order dated November 27, 1990 and NOV #N91-20-1-1. Concerns about the plates have arisen (e.g., missing information, disagreement between overlaps and the inability for the plates to be self-explanatory). Therefore, the review has stopped until the plates are corrected.

Please call me about arranging a meeting to discuss the problems with these plates. All plates will need to be corrected and re-submitted in order to reinstate the review.

Sincerely,

A handwritten signature in cursive script, reading "Pamela Grubaugh-Littig".

Pamela Grubaugh-Littig
Permit Supervisor

jbe
cc: Lowell Braxton
Tom Munson
Hugh Klein

AT015025.005