

0003

MEC Mangum
Engineering
Consultants

*Copy PAM,
File ACT/015/025.*

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

#2

6 January 1992

Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

RECEIVED

JAN 06 1992

DIVISION OF
OIL GAS & MINING

Dear Ms. Grubaugh-Littig:

Re: Updated Plates, Bear Canyon Mine, Co-Op Mining Company,
ACT/015/025, Emery County, Utah

Attached are two copies of Plates 3-4 and 8-5A. Plate 3-4 is updated to show the mining progress in 1991. Plate 8-5A rev. 1 was submitted in "DRAFT" last week and the "Reclamation/Disturbed Area" boundary was incorrectly drawn at the Ball Park. Please discard the previous Plate 8-5A rev. 1.

There have been numerous submittals made in the last few months. Please notify me in writing which submittals have been approved with page/Plate numbers so I can send copies without the "DRAFT" mark.

Thank you,



Kimly C. Mangum, P.E.
Permitting & Compliance Consultant.

Enclosure(s)
cc: Co-Op Mining Co.