

0077

ACT/015/025
file folders #2 & #5

MEEC Mangum
Engineering
Consultants

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

11 May 1992

Pamela Grubaugh-Littig
Permit Supervisor
Utah Division of Oil Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203


Dear Pamela:,

Re: NOV # N92-40-9-1, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025, Emery County, Utah

It was pointed out by Hugh Klein of the Division in a conversation with Charles Reynolds this afternoon that the design of ditch D-10aU was not included with the recent submittal. Attached are two copies of pages 7-87, and 77a from Appendix 7-G. These pages include the design of D-10aU. Two copies of Plate 8-5B with the proper areas stippled to indicate areas not requiring recontouring will also be delivered to your office this afternoon.

Copies of the proposed revised pages and plates have been marked "DRAFT" to differentiate them from those previously approved. Additional copies will be forwarded to the Division upon receipt of written approval. Please identify approved pages and plates by number and revision. Please notify me if there are any open issues concerning abatement of this violation.

Thank you,



Kimly C. Mangum, P.E.

cc: Co-Op Mining Co.

RECEIVED

MAY 19 1992

DIVISION OF
OIL GAS & MINING