

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

17 July 1992

Pamela Grubaugh-Littig  
Permit Supervisor  
Utah Division of Oil Gas & Mining  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203

**RECEIVED**

JUL 20 1992

DIVISION OF  
OIL GAS & MINING

Dear Pamela:

Re: Abatement of NOV #N91-35-8-1 & Compliance with Division Order DO-92C, Co-Op Mining Company, Bear Canyon Mine, ACT/015/025, Emery County, Utah

This submittal is made at the request of Co-Op Mining Co to address the issues referenced in a memo from Hugh Klein of the Division dated 14 July 1992. There are 5 issues listed in the memo. Each one was also discussed during a visit to your office 16 July 1992.

1. Pages 7-87A: This table, Table 7.2-10 has been resubmitted along with a new set of calculations for all of the diversions. A copy of the table is enclosed.
2. Plate 7-1C: The lower diversion marked D-10D is actually D-10aD. This will be corrected in the Plates to be sent to the Division next week. The last section of C-2U will also be labeled as requested.
3. Page 7-104: The figure on this page was deleted so the page will be blank. A copy was given to Hugh yesterday. Two copies are enclosed.
4. Page 6 in Appendix 7F: EarthFax has corrected page 6 and 7. A copy was given to Hugh yesterday. Two copies are enclosed.
5. Page 14 in Appendix 7G: The printout rounded off the value to zero. The actual value has been added. Two copies are enclosed.

Copies of the updated plates will be delivered the first of next week and may reach your office before this letter. I appreciate your recent efforts to close these issues. Please call if there area nay additional concerns.

Thank you,



Kimly C. Mangum, P.E.

cc: Co-Op Mining Co.