

0007



United States Department of the Interior



BUREAU OF LAND MANAGEMENT

Moab District
P.O. Box 970
Moab, Utah 84532

IN REPLY REFER TO:

3482
U-024316
U-46484
U-020668
(UT-066)

Ms. Pamela Grubaugh-Littig
Permit Supervisor
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 150
Salt Lake City, Utah 84180-1203

RECEIVED

JAN 21 1994

JAN 24 1994

ACT 1018/025

CEP-94A

DIVISION OF
OIL, GAS & MINING

Dear Ms. Grubaugh-Littig:

Co-OP Mining Company (Co-OP) proposes to drill three truck-mounted rotary coal exploration drill holes on Gentry Mountain, and one helicopter drill hole on Wildhorse Ridge. All of these coal exploration drill holes will be completed as water monitoring wells. All four coal exploration drill holes are located on Federal coal leases (U-46484, U-024316 and U-020668) outside of a permit area.

Please review this exploration plan (two copies enclosed), and provide any recommended conditions of approval to this office.

If you have any questions regarding this matter, contact Tom Rasmussen at the Price River Resource Area (637-4584).

Sincerely,

District Manager

Acting

Enclosure

Exploration Plan (29 pp), two copies

cc: UT-066, Price River Resource Area (wo/Enclosures)

UT-921, Branch of Mining Law and Solid Minerals, Utah State Office (wo/Enclosures)