

0027



CASTLE VALLEY SPECIAL SERVICE DISTRICT

P. O. BOX 877
CASTLE DALE, UTAH 84513
TELEPHONE (435) 381-5333

FAX # (435) 381 5345

PAUL CRAWFORD
Chairman
DARREL V. LEAMASTE
Manager

Darrel
8/15/2004

FAX TRANSMITTAL

Date: Aug 13, 2004

To: Wayne Hedberg FAX # 801-~~801~~-359-3940

Agency/Firm: Oil Gas & Mining

Phone Number _____

Number of Pages _____
(including cover page)

Subject: Abandoned Equipment
Bear Canyon Mine

RECEIVED

AUG 13 2004

DIV. OF OIL, GAS & MINING

I just noticed a big discrepancy
between CW Mining's letter to the
EPA and Oil Gas & Mining's
Technical Analysis on the
quantity of lead. CW Mining
says the lead quantity is 8,768# and
Oil Gas & Mining says 17,536#.
Which is correct? Also look
at the sulfuric acid quantities.

FROM: _____

Darrel Leamaster