



0011

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & MiningACT/015/032
File # 2 d #
Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

April 7, 1988

TO: File

FROM: James Leatherwood, Reclamation Soils Specialist 

RE: New Lease U054762 Proposal Review, Genwal Coal Company, Crandall Canyon Mine, ACT/015/032, Folder #2, Emery County, Utah

The above-mentioned New Lease Proposal submitted in the Permit Application Package (PAP), February 16, 1988, has been reviewed and found not to be complete. The following items must be addressed.

UMC 783.24 Maps: General Requirements - JSL

The permit boundary delineation for lease U054762 on Plate 2-1 and Plate 3-3 is different than plates 2-2 and 3-10. The PAP must include the correct legal permit lease boundary.

UMC 786.11 Public Notices of Filing of Permit Applications - JSL

The PAP must include a revised public notice newspaper advertisement to include the new lease area, U054762. This public notice must contain all pertinent information as required under UMC 786.11.

Other Agency Comments

The Division of State History (see enclosed) recommends that a cultural resource survey of the areas previously not surveyed be conducted to make a determination on historic properties.

jr
Enclosure
cc: S. Linner
0534R/75