

0021

**GENWAL COAL COMPANY**

*Act/015/032
#2
cc: Hadelock*

Sept. 4, 1990

Craig Cox
Utah Power and Light
1407 West North Temple - Room 3306
Salt Lake City, Utah 84140

Re: Special use permit from U.S. Forest Service for the Genwal Coal Company, Crandall Canyon mine powerline installation.

Dear Mr. Cox,

We understand that the construction of the Crandall Canyon powerline project is covered by a special use permit issued to UP&L by the U.S. Forest Service.

Likewise, Genwal Coal Company conducts day to day business under the parameters of several mining related permits (DOGM permit, special use permits, etc.). These permits serve as a guideline to conduct mining operations in Crandall Canyon. It has been brought to my attention that there may be a potential conflict between our DOGM permit and your special use permit as it pertains to the installation and anchoring of your triple pole combination located on the upper bench area of the mine site.

To clarify this matter, I would request of you, a copy of your special use permit, to allow us to be informed of each others intentions and requirements as in pertains to the powerline installation on the Genwal mine site.

Should you have any question or need to contact me personally, please call me at 687-9813.

Sincerely,

Allen P. Childs
General Manager
Genwal Coal Company

ACT/015/032
#5
cc: Lynn Kunzler

GENWAL COAL COMPANY

August 30, 1990

RECEIVED
AUG 31 1990

Mr. Lowell Braxton
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, Utah 84180-1203

DIVISION OF
OIL, GAS & MINING

RE: NOV. N90-17-3-2 Abatement Extentions

Dear Mr. Braxton:

At this time, Genwal Coal Company would formally request of you and the division an extension date of Sept. 14, 1990, for submission of an as-built surface facilities map (line item #2 of NOV. N90-17-3-2).

To provide this surface facilities map, Genwal Coal Co. has surveyed, targeted and had Olympus Aerial, fly the surface area using aerial photography. The area was flown on Aug. 24, 1990. Olympus Aerial is in the process of digitizing our surface facilities map. Olympus Aerial and Genwal Coal Co. have been transmitting information back and forth via Federal Express. This process has cost us time, and as a result slowed the mapping process down.

As per conversations with Mr. Maurice Pia of Olympus, it has become evident that the Aug. 31, submittal date cannot be met by Olympus. Mr. Pia has committed to us, that the drawing will be made available to the DOGM by Sept. 14, 1990.

Due diligence on this remedial action, will be maintained to ensure delivery of the surface facilities map on or before the requested extension date.

Your approval of this extension date will be greatly appreciated.

Should you have any questions or need any additional information, please contact me at 687-9813 at your convenience.

Sincerely,



Allen P. Childs
Vice Pres./Mine Manager

APC/cc
enclosures

NOTICE OF VIOLATION NO. N90-17-3-2

Violation No. 2 of 2

Nature of violation

Failure to obtain permit amendment prior to constructing new facilities

Provisions of act, regulations or permit violated

R614-300-112.400
R614-300-141

Portion of operation to which notice applies

Substation and power poles on oil substation pad.

Remedial action required (including any interim steps)

1. Submit ^{as built} plans to the Division for review and approval.
2. revise surface facilities map to show these facilities and show area of past permanent revegetation ^(upper pad) now being used for these facilities
3. Reseed disturbed area around poles

Abatement time (including interim steps)

By 4:00 PM on Friday August 31, 1990, for steps #1 & #2

by 4:00 PM on October 31, 1990, for step #3



AERIAL SURVEYS INC.

50 WEST 2950 SOUTH
SALT LAKE CITY, UTAH 84115
PHONE 801 484-4351

484-4353

WORK ORDER AND AGREEMENT

Mr. Alan Childs
Genwall Coal Company
100 North 100 West
Huntington, Utah 84528

Date Aug. 20, 1990

Job No. 90083

Documents Received From Client: Verbal description of revision work to be done.

Location of Work: Crandall Canyon & vicinity.

Scope of Work: Secure new aerial photography of Crandal Canyon surface facilities on the mine site. Using the new photography and existing control your surveyors will flag, Olympus will update the existing 1988 map to show all changes visible on the new photography.
(Map is 1"=40' with 2' contours.)

All work performed will be in accordance with accepted standards of professional practice. All manuscripts, film and original documents are the property of OLYMPUS AERIAL SURVEYS, INC., except where by law or precedent these documents become public property or except when agreed in advance.

"Standard procedure dictates that photogrammetric maps be field-checked prior to use. Failure to notify us within sixty (60) days of any errors and/or omissions, shall be deemed an acceptance of the maps and any claims as a result of such defects are waived."

The above described services will be performed by OLYMPUS AERIAL SURVEYS, INC., for the fee of \$1,375.00, Thirteen hundred seventy-five and no/100, payable immediately on receipt of invoice. All amounts not paid within thirty (30) days become subject to a 1% per month service charge on the unpaid balance until paid in full. In the event any action be brought on this agreement or amount due hereunder, client agrees to pay all litigation costs and collection expenses, including but not limited to reasonable attorney fees.

If this Work-Order and Agreement correctly summarizes our understanding of the scope of work you have requested, please sign it and return one copy as our authorization to proceed. This agreement shall be deemed entered into when it is received at Olympus Aerial Surveys, DULY SIGNED BY THE CLIENT RESPONSIBLE FOR PAYMENT. (If different than above, please include full name, address and phone no.)

OLYMPUS AERIAL SURVEYS, INC.

By [Signature]

Title President

Date Aug. 20, 1990

PARTY RESPONSIBLE FOR PAYMENT

CLIENT: Genwall Coal Co.

By [Signature]

Title Mine Manager

Date 8-24-90