

0005



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

bcc
Mary ANN
Pam G
DAVE

November 23, 1999

CERTIFIED RETURN RECEIPT
P 074 978 539

Gary Gray, Resident Agent
Genwal resources, Inc.
P.O. Box 1420
Huntington, Utah 84528

Re: Division Order -DO99A, Genwal Resources, Inc., Crandall Canyon Mine, ACT/015/032-DO99A, Folder #3, Emery County, Utah

Dear Mr. Gray:

I am enclosing Division Order ACT/015/032-DO99A relative to clarifying water monitoring for the Crandall Canyon Mine. At a meeting with Pamela Grubaugh-Littig, Ken Wyatt, Dave Darby and Steve Demczak on October 28, 1999, they explained to you the need for clarification on your water quality monitoring and a water monitoring table to easily identify the schedule.

Please respond to this Division Order within 60 days of receipt. If you have any questions, please call Pamela Grubaugh-Littig.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Lowell P. Braxton', written over a faint circular stamp.

Lowell P. Braxton
Director

sm
Enclosure
cc: Price Field Office
*O:\015032.CRA\FINAL\DO99A\tr.wpd

SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4.

Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge)
2. Restricted Delivery (Extra charge)

3. Article Addressed to:

GARY GRAY
GENVAL RESOURCES, INC
P O BOX 1420
HENTINGTON UT 84528

4. Article Number
P 074 978 539

Type of Service:
 Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

Always obtain signature of addressee or Agent and DATE DELIVERED

5. Signature - Address
X

6. A **NO** fee is charged (ONLY if requested and fee paid)

6. Signature - Agent
X *[Handwritten Signature]*

7. Date of Delivery

USPS - 84528

PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212-865 DOMESTIC RETURN RECEIPT

111 1109M ACT / 015 / 030 11-24-99 SM 43

UNITED STATES POSTAL SERVICE

OFFICIAL BUSINESS

SENDER INSTRUCTIONS
 Print your name, address and ZIP Code in the space below.

- Complete items 1, 2, 3, and 4 on the reverse.
- Attach to front of article if space permits; otherwise affix to back of article.
- Endorse article "Return Receipt Requested" adjacent to number.

HUNTINGTON UT



DEC - 1 1999 NOV 29 1999

PENALTY FOR PRIVATE MAIL \$300

DIV. OF OIL, GAS & MINING
 Print sender's name, address, and ZIP Code in the space below.

RETURN TO →

DIVISION OF OIL, GAS & MINING
 1594 W NO TEMPLE STE 1210
 SLC UT 84114

ATTEN:



**STATE OF UTAH
DIVISION OF OIL, GAS AND MINING**

PERMITTEE

Gary Gray, Resident Agent
Genwal Resources, Inc.
P.O. Box 1420
Huntington, Utah 84528

**ORDER & FINDINGS
OF
PERMIT DEFICIENCY**

PERMIT NUMBER ACT/015/032

DIVISION ORDER 99A

PURSUANT to R645-303-212, the Division orders the permittee, Genwal Resources, Inc., to make the requisite permit changes enumerated in the findings of Permit Deficiency in order to be in compliance with the State Coal Program. These findings are to be remedied in accordance with R645-303-220.

FINDINGS OF PERMIT DEFICIENCY

A review of the current Mining and Reclamation Plan (MRP) and field investigations have revealed that certain activities associated with the mine are not adequately addressed in the operation and reclamation plan.

Information Required to Be Submitted by Regulation Cited:


R645-301-731. The ground and surface water monitoring plans for the Crandall Canyon Mine do not provide a clear and concise description of the water monitoring locations, the required monitoring frequency and the specific parameters associated with each sample location. The MRP lacks a table of surface and ground water sites and the appropriate parameters to be analyzed with each sample. The Division hereby requires the ground and surface water monitoring plans be amended to include a clear and concise description of the water monitoring plans.

R645-301-521.162 and R645-301-521.163. The map in the operation and reclamation plan showing the water monitoring locations should be updated to reflect the current and new water monitoring locations. Sites not being monitored should be removed from this map.

ORDER

Genwal Resources, Inc., is hereby ordered to make the requisite permit changes in accordance with R645-303-220 and to submit a complete, adequate application for permit change to address the findings of permit deficiency within 60 days of the date of receipt of this order.

Ordered this 23rd day of November, 1999, by the Division of Oil Gas, and Mining.


for _____
Lowell Braxton, Director
Division of Oil, Gas and Mining