

0052



State of Utah

Department of  
Natural Resources

ROBERT L. MORGAN  
*Executive Director*

Division of  
Oil, Gas & Mining

MARY ANN WRIGHT  
*Acting Division Director*

OLENE S. WALKER  
*Governor*

GAYLE F. McKEACHNIE  
*Lieutenant Governor*

December 21, 2004

Gary E. Gray, Resident Agent  
Genwal Resources, Inc.  
P.O. Box 1077  
Price, Utah 84501

Re: Updated Surface Facility Map, Genwal Resources, Inc., Crandall Canyon Mine, C/015/0032, Task ID #2064

Dear Mr. Gray:

Plate 5-3 is the Surface Facilities Map contained in the approved mining and reclamation plan. Revisions to this map have been made to reflect material placement in the upper pad/coal storage pad. The revisions were made using survey data taken on the pad areas. This item is a follow up item connected to the South Portal construction that was initiated in 2002.


The certification requirements are met. Plate 5-3 is certified. This certification is by a registered professional engineer in the State of Utah. There are no changes to the TA dated December 8, 2004.

The above-referenced amendment is conditionally approved upon receipt of seven clean copies prepared for incorporation. Please submit these copies by January 21, 2005. Once we receive these copies, final approval will be granted, at which time you may proceed with your plans.

A stamped incorporated copy of the approved plans will also be returned to you at that time, for insertion into your copy of the Mining and Reclamation Plan. A copy of our Technical Analysis is enclosed.

If you have any questions, please call me at (801) 538-5268 or Karl R. Houskeeper at (435) 613-1146, Ext 201.

Sincerely,

  
Pamela Grubaugh-Littig  
Permit Supervisor

sd  
cc: Price Field Office  
O:\015032.CRA\FINAL\WG2064\CONAPP\_2064.DOC