

# TECHNICAL MEMORANDUM

Utah Coal Regulatory Program

---

OK

November 14, 2006

TO: Internal File

THRU: Pamela Grubaugh-Littig, Permit Supervisor *pgl*

FROM: Wayne H. Western, Team Lead *W H W*

RE: Revised Surface Facility Map, Genwal Resource Inc., Genwal Mine, C015/0032, Task ID #2678

**SUMMARY:**

On October 25, 2006, the Division received an application to update the surface facilities map. The Permittee revised the surface facilities map because some on the ground facilities were not shown on the map.

**TECHNICAL MEMO**

---

**TECHNICAL ANALYSIS:**

**OPERATION PLAN**

**MAPS, PLANS, AND CROSS SECTIONS OF MINING OPERATIONS**

Regulatory Reference: 30 CFR Sec. 784.23; R645-301-512, -301-521, -301-542, -301-632, -301-731, -302-323.

**Analysis:**

**Mining Facilities Maps**

The Permittee met the requirements for the surface facilities maps. The map that the Permittee submitted accurately shows the on the ground facilities.

**Certification Requirements**

The Permittee met the requirements for certifying the surface facilities map.

**Findings:**

The Permittee meet the minimum requirements of the minimum requirements for maps, plans and cross sections of mining operations.

**RECOMMENDATIONS:**

The Division should approve the amendment.