

OGMCOAL - Re: I so appreciate you getting back to me

From: Daron Haddock
To: Bobbi Bryant
Date: 2/17/2011 2:29 PM
Subject: Re: I so appreciate you getting back to me
CC: Joe Helfrich; OGMCOAL
Attachments: 5 - DWG. 5 - 2.pdf

Hi Bobbi,

I have attached the Disturbed sequence map that was submitted for the Coal Hollow Mine. I hope it provides the information you are looking for. My understanding is that the 635 acres that are permitted encompass the entire lease area where the company has acquired right-of-entry. Not all of the permit area will be disturbed. In fact only 435 total acres are planned for disturbance and of that only 289 acres will be disturbed in the first year. When the inspection report refers to 435 acres of disturbance, this is the area that is projected for disturbance, not what has actually been disturbed. Right now the company has only bonded for 289 acres of disturbance and that is the limit that is allowed until additional bond is posted or previous disturbance has been reclaimed.

I am not aware that they have a crusher or scrubber on site. I will check with Joe Helfrich when he gets back from his inspection. I suppose they could truck the coal without it being crushed, but it is not likely since their contract would probably call for certain size specifications. There is nothing in our regulations that would require any coal to be processed before it was shipped. I hope this helps.

Daron R. Haddock
Coal Program Manager
Utah Division of Oil, Gas & Mining
(801) 538-5325

>>> Bobbi Bryant <brincobobbi@gmail.com> 2/17/2011 11:56 AM >>>

Hi Daron - Hate to be a pest but I try to have accurate information before I share it with other people in general conversation. You say the bond is for the 289 acres but the reports show 435 disturbed of 635.64 permitted. So am I to assume that the total amount to be disturbed is 435 not the 635.64?

Also, do you know if they have the crushed and scrubber in place. Can they load and truck coal without these in place?

Thanks

