

2

Outgoing  
C0250005  
#3773 R

 <b>Action Taken on Existing Citation</b> <b>Utah Coal Regulatory Program</b> 1594 West North Temple, Salt Lake City, UT 84114 Phone: (801) 538 - 5285 Fax: (801) 359-3940	<b>Action on Citation#:</b> <b>10079</b>
	<b>Permit Number:</b> <b>C0250005</b>
	<b>Date Cit. Issued:</b> <b>03/09/2011</b>

<input type="checkbox"/> <b>MODIFICATION of</b>	<input checked="" type="checkbox"/> <b>TERMINATION of</b>	<input type="checkbox"/> <b>VACATION of</b>
---	---	---

<input checked="" type="checkbox"/> <b>NOTICE OF VIOLATION</b>	<input type="checkbox"/> <b>CESSATION ORDER (CO)</b>	<input type="checkbox"/> <b>FAILURE TO ABATE CO</b>
--	--	---

<b>Permittee Name:</b> ALTON COAL DEVELOPMENT LLC	<b>Inspector Number and ID:</b> 1 JHELFRIC
<b>Mine Name:</b> COAL HOLLOW	<b>Date and Time of Action:</b>
<b>Certified Return Receipt Number:</b>	<b>Date and Time of Service:</b>

*In accordance with the provisions of the Utah Coal Mining and Reclamation Act, Utah Code Ann. § 40-10-1 et. seq. (Act), the above referenced Citation is:*

**Modified as follows:**

  
  
  
  
  
  
  
  
  
  

**Reason for modification:**

**Terminated because:**  
 Topsoil had been removed, stockpiled and protected in topsoil stockpile #2. The subsoil is to remain in place. Several "do not enter" signs have been placed at the edge of the subsoil area and the area has been bermed.

**Vacated because:**

<b>Kirk Nicholes</b> (Print) Permittee Representative	<b>JOE HELFRICH</b> (Print) DOGM Representative
_____ Permittee Representative's Signature - Date	<i>Joseph C Helfrich</i> 6/27/2011 _____ DOGM Representative's Signature - Date

**Refer to the "Citation For Non-Compliance" for additional information**