

 <p>UTAH DNR OIL, GAS & MINING</p>	<p>Citation for Non-Compliance Utah Coal Regulatory Program 1594 West North Temple, Salt Lake City, UT 84114 Phone: (801) 538-5340 Fax: (801) 359-3940</p>	<p>Citation #: 16149</p>
		<p>Permit Number: C0250005</p>
		<p>Date Issued: 01/26/2015</p>
<p> <input checked="" type="checkbox"/> NOTICE OF VIOLATION <input type="checkbox"/> CESSATION ORDER (CO) <input type="checkbox"/> FAILURE TO ABATE CO </p>		
<p>Permittee Name: ALTON COAL DEVELOPMENT LLC</p>		<p>Inspector Number and ID: 37 PBURTON</p>
<p>Mine Name: COAL HOLLOW</p>		<p>Date and Time of Inspection: 01/12/2015 11:30 am</p>
<p>Certified Return Receipt Number: 7008 0150 0002 0896 5328</p>		<p>Date and Time of Service: 01/26/2015 4:00 pm</p>
<p>Nature of condition, practice, or violation: Alton Coal Development, LLC failed to follow approved plans for reconstruction of Lower Robinson Creek which require an even slope of -2.5% from the beginning point to the end point, rip rap in the channel bottom, a 10:1 flood plain, and erosion control mat as shown on Drawings 5-20A and 5-21A. This combination of grade, channel, bank and floodplain configuration was certified by a professional engineer.</p>		
<p>Provisions of Act, regulations, or permit violated: R645-300-142 and R645-301-742.313 and R645-301-742.320 et seq.</p>		
<p><input type="checkbox"/> This order requires Cessation of ALL mining activities. (Check box if appropriate.)</p>		
<p><input type="checkbox"/> Condition, practice, or violation is creating an imminent danger to health or safety of the public.</p>		<p><input type="checkbox"/> Permittee is/has been conducting mining activities without a Permit.</p>
<p><input type="checkbox"/> Condition, practice, or violation is causing or can reasonably be expected to cause significant, imminent environmental harm to land, air, or water resources.</p>		<p><input type="checkbox"/> Permittee has failed to abate Violation(s) included in <input type="checkbox"/> Notice of Violation or <input type="checkbox"/> Cessation Order within time for abatement originally fixed or subsequently extended.</p>
<p><input type="checkbox"/> This order requires Cessation of PORTION(S) of mining activities.</p>		
<p>Mining activities to be ceased immediately: <input type="checkbox"/> Yes <input type="checkbox"/> No</p>		<p>Abatement Times (if applicable).</p>
<p>Action(s) required: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p> <p>The current construction differs from the approved, P.E. stamped designs found on Dwg. 5-20A and 5-21A of the MRP. ACD must either implement the approved plan or have a professional engineer evaluate the channel as currently constructed to provide certified, design drawings of the new configuration, including interim sediment control requirements within the channel and at the permit boundary, and to amend Appendix 5-3 supporting documentation for the design. A qualified registered professional engineer must certify that the new design meets the requirements of R645-301-742-320 et seq and the performance standards of R645-301-750 and the new design must be submitted to the Division by March 12, 2015 (45 days) for approval.</p>		
<p>Kirk Nichols _____ (Print) Permittee Representative</p>		<p>PRISCILLA BURTON _____ (Print) DOGM Representative</p>
<p>Permittee Representative's Signature - Date</p>		<p><i>Priscilla Burton</i> 1/26/15 _____ DOGM Representative's Signature - Date</p>
<p><u>SEE REVERSE SIDE Of This Form For Instructions And Additional Information</u></p>		

