



**Action Taken on Existing Citation
Utah Coal Regulatory Program**

1594 West North Temple, Salt Lake City, UT 84114
Phone: (801) 538 - 5285 Fax: (801) 359-3940

Action on Citation#: **21191**
Permit Number: **C0250005**
Date Cit. Issued: **12/07/2016**

| | | |
|---|--|--|
| <input type="checkbox"/> MODIFICATION of | <input checked="" type="checkbox"/> TERMINATION of | <input type="checkbox"/> VACATION of |
| <input checked="" type="checkbox"/> NOTICE OF VIOLATION | <input type="checkbox"/> CESSATION ORDER (CO) | <input type="checkbox"/> FAILURE TO ABATE CO |

| | |
|--|---|
| Permittee Name: ALTON COAL DEVELOPMENT LLC | Inspector Number and ID: 37 PBURTON |
| Mine Name: COAL HOLLOW | Date and Time of Action: 12/08/2016 3:00 pm |
| Certified Return Receipt Number: e-mailed | Date and Time of Service: 01/26/2017 11:50 pm |

In accordance with the provisions of the Utah Coal Mining and Reclamation Act, Utah Code Ann. § 40-10-1 et. seq. (Act), the above referenced Citation is:

Modified as follows:

Reason for modification:

Terminated because:
The topsoil and berm were observed above the highwall of Pit 6 on January 25, 2017. The surveyed location of the new topsoil berm was provided on January 25, 2017. The placement of the surveyed track onto Dwg 5-47 (dated 12-14-2016) establishes the current extent of the North Lease topsoil pile. A comparison of the current extent of the pile with the contours of the pile shown on Dwg 5-47 shows the topsoil was removed from the highwall. (The highwall has since advanced to the berm.)

Vacated because:

KIRK NICHOLAS
(Print) Permittee Representative

PRISCILLA BURTON
(Print) DOGM Representative

Permittee Representative's Signature - Date

DOGM Representative's Signature - Date

Refer to the "Citation For Non-Compliance" for additional information