

0013



**Southern Utah
Fuel Company**
P.O. Box P
Salina, Utah 84654
(801) 529-7428
(801) 637-4880 (Mine)

*File ACT/041/002
w/ map
Copy to Dave D. &
Ken w/ maps (1ea)*
**Subsidiary of
Coastal States
Energy Company**

JIM

JUL 0 1 1982

June 28, 1982

Mr. Jim Smith
Division of Oil, Gas and Mining
4241 State Office Building
Salt Lake City, Utah 84114

RECEIVED

JUN 30 1982

**DIVISION OF
OIL, GAS & MINING**

RE: Lower Mine Yard Drainline

Dear Jim:

In response to an onsite request by Ken Wyatt for plans of our mine yard drainline, I am sending the enclosed six copies of our mine yard map. The drainlines shown on the map are installed and working properly.

The lower mine yard drainage system consists of a ten inch steel pipeline with drain sumps which collect from all of our upper yard drainlines. The pipe conveys the water through the lower yard and discharges directly into the sediment trap. This drainline eliminates the muddy conditions caused by the previous open channel drainage system through the lower mine yard. The drainline should improve the sediment pond discharge water quality by eliminating part of the sediment picked up as the water flows over the yard surface.

If there are any questions or comments, please contact me.

Sincerely,

Kerry Frame
Chief Engineer

MLD:d1j

Enclosures