



0007

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*File*

*SU*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84103 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: March 17, 1988  
11:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Southern Utah Fuel Co.  
Business Address: P.O. Box P Salina, Utah 84654  
Mine Name: Convulsion Canyon Permit Number: ACT/041/002  
Type of Mining Activity: Underground  Surface  Other   
County: Sevier State Utah  
Company Official (s): Mike Davis and Chris Kravits  
State Official(s): Daron Haddock  
Partial:  Complete:  Date of Last Inspection: Jan. 27-28, 1988  
Weather Conditions: Clear, sunny, cool  
26°F  
Acreage: Permitted 7355 Disturbed 17 Regraded  Seeded  Bonded 27.9  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( X )	( )	( )	( X )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( X )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( X )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION March 17, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

A recent snowstorm has left two to three inches of snow over much of the site.

1. PERMITS:

Responses to the two outstanding five-year permit conditions were submitted to DOGM on February 25, 1988. (Condition UMC 817.52-(1)-DD and Condition USFS 3.) DOGM is in the process of reviewing the submittals.

A revised PAP amendment for the 4 East ventilation portal located in Quitchupah Canyon was submitted on February 25, 1988, and is also being reviewed by DOGM.

2. SIGNS AND MARKERS:

Disturbed area perimeter markers are in place and visible.

3. TOPSOIL:

In regards to TDN 88-2-6-1 2 of 2, the operator is planning to meet the March 31 deadline for submitting an amnedment to the plan addressing topsoil storage.

4b. DIVERSIONS:

Snowmelt and runoff is all passing through the sediment trap and the sediment pond. A drop drain north of the processing facility appears to be plugged; however, no significant problem to the overall drainage pattern is apparent. I asked Mr. Davis and Mr. Kravits to have the drain cleared.

INSPECTION REPORT  
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION March 17, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

4c. SEDIMENT PONDS:

The sediment pond is nearly full of water but is not discharging. The last pond inspection was performed February 1, 1988. A report was submitted the same day.

4f. EFFLUENT LIMITATIONS:

An NPDES report was sent on February 29, 1988, showing no discharge from point 001 or point 002. Point 003 was discharging within the limits of the NPDES permit.

9. PROTECTION OF FISH, WILDLIFE, AND RELATED ENVIRONMENTAL VALUES:

Seven head of deer were spotted grazing near the sediment pond and topsoil storage area.

Copy of this Report:

Mailed to: Mike Davis, SUFCO

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Daron Haddock #28 Date: March 18, 1988