



## State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MININGNorman H. Bangerter  
GovernorDee C. Hansen  
Executive DirectorDianne R. Nielson, Ph.D.  
Division Director355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

November 7, 1991

Mr. Ken Payne, Manager  
Southern Utah Fuel Company  
P. O. Box P  
Salina, Utah 84654

Dear Mr. Payne:

Re: Deficiency, Updated Facilities Map, Southern Utah Fuel Company, Convulsion Canyon Mine, ACT/041/002, Folder #2, Sevier County, Utah

On October 31, 1991 the Division received the enclosed copies of your updated Facilities Location Map number 80-4D. The maps as submitted cannot be accepted by the Division and are hereby being returned for your further attention.

Some of the problems with the maps include the following:

- \* No certification by a registered professional engineer.
- \* No indicator of the disturbed area boundary.
- \* No indicator of permit boundary (applicable if boundary crosses through area shown on map).

It would also be helpful if the map referenced other maps showing all areas of disturbance for the entire mine. Please correct the above deficiencies and resubmit the maps by December 6, 1991. If you have any questions, please contact Randy Harden of the Division's technical staff.

Sincerely,

A handwritten signature in cursive script that reads "Daron R. Haddock".

Daron R. Haddock  
Permit Supervisor

Enclosures  
cc: R. Harden  
SUFCMAPS.LET