

0021



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801

(801) 538-5340

(801) 359-3940 (Fax)

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

November 10, 1997

To: File

Thru: Joe Helfrich, Permit Supervisor-Compliance *JH*

From: Peter Hess, Reclamation Specialist III *PHB*

RE: Ditch Designs for MSH-2A and DIS-1A, Plate 7-6, East Spring Canyon Drainage Details, Canyon Fuel Company, LLC, SUFCO Mine, ACT/041/002-97C, Folder #2, Sevier County, Utah

In response to N97-46-4-3, 3 of 3, "Failure to Provide Accurate Surface Drainage Maps", SUFCO has submitted a revised Plate 7-6 which shows the correct flow directions for the interception ditch from watershed MSH-2 and ESC-6. The revision of Plate 7-6 also included the addition of ditch DIS-1A, a diversion which had been implemented in the field, but for which no design existed in the mining and reclamation plan.

Based on the fact that the permittee had revised Plate 7-6 to show correct flow directions and had added ditch DIS-1A, N97-46-4-3, 3 of 3 was terminated on November 6, 1997.

The enclosed hydrology amendment provides the designs for ditches MSH-2 and DIS-1A. Please have Mr. Mike Suflita review same and respond as to the adequacy of this submittal. SUFCO has submitted eight copies, seven of which I am forwarding to the DOGM SLO.

Thank you for your attention to this amendment.

sd
enclosure