



Canyon Fuel Company, LLC
 SUFCO Mine
 397 South 800 West
 Salina, Utah 84654
 (435) 637-4880 Fax: (435) 636-4499

December 10, 2003

Utah Coal Program
 Utah Division of Oil, Gas, and Mining
 1594 West North Temple, Suite 1210
 Box 145801
 Salt Lake City, Utah 84114-5801

*Incoming
 c/o 41/0002*


Dear Program Supervisor:

The mine site sedimentation pond has been cleaned out to approximate its designed configuration. This work was completed in late October 2003. The damage to the emergency spillway noted in the annual inspection was also repaired. The v-notch outlet weir was also replaced during the cleaning operation.

Sincerely,
 CANYON FUEL COMPANY, LLC
 SUFCO Mine

Wesley K. Sorensen

Wesley K. Sorensen, P.E.
 Utah Registration No. 159457
 Director of Process Improvement



WKS:kb

cc: DOGM Sediment Pond Inspection File
 Mike Davis
 Craig Hilton

RECEIVED

DEC 16 2003

DIV. OF OIL, GAS & MINING