



## State of Utah

### Department of Natural Resources

MICHAEL R. STYLER  
*Executive Director*

### Division of Oil, Gas & Mining

MARY ANN WRIGHT  
*Acting Division Director*

JON M. HUNTSMAN, JR.  
*Governor*

GARY R. HERBERT  
*Lieutenant Governor*

March 15, 2005

Ken May, General Manager  
Canyon Fuel Company, LLC  
397 South 800 West  
Salina, Utah 84654

Subject: Surface Facility Update, Canyon Fuel Company, SUFCO, C/041/0002, Task ID #2130, Outgoing File

Dear Mr. May:

The above-referenced amendment has been reviewed. There are deficiencies that must be adequately addressed prior to approval. A list of those deficiencies is as follows:

**R645-301-526**, The Permittee must update Table 5-4 and Plate 5-2A and Plate 5-2B so that all physical facilities East Canyon listed on the table and maps. In addition, the Permittee must also include subsection in Table 5-4 for physical facilities that are located in remote areas such as Link Canyon.

**R645-301-521.160 and R645-301-521.190**, The Permittee must label each facility on Plate 5-2A and Plate 5-2B according to the name given in Table 5-4.

**R645-301-830.140**, The Permittee must update the reclamation cost estimate to include all physical facilities listed on Table 5-4. The Permittee must verify that the volumes and material types given are correct.

In order for us to continue to process your application, please respond to these deficiencies by April 4, 2005.

If you have any questions, please call me at (801) 538-5286 or Pete Hess at (435) 613-1146. If you have specific questions about what items were not on Table 5-4 or items not labeled or missing from Plate 5-2A and Plate 5-2B please call Wayne Western at (801) 538-5263.

Sincerely,

D. Wayne Hedberg  
Permit Supervisor

an  
cc: Price Field Office  
O:\041002.CON\FINAL\2130\Defletter2130.doc