



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitchupah Monitoring

Vicky Miller <vmiller@bowieresources.com>

Mon, Mar 23, 2015 at 11:51 AM

To: "Steve Christensen (stevechristensen@utah.gov)" <stevechristensen@utah.gov>, "Amanda Daniels (amandadaniels@utah.gov)" <amandadaniels@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>

Cc: "OGMCOAL OGMCOAL (OGMCOAL@utah.gov)" <OGMCOAL@utah.gov>, Wyatt Shakespear <WShakespear@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>

We have been unable to access South Fork during the past two weeks (3/9, 13, 16 & 19), warmer temperature and melting snow have complicated the mud situation. The one access was still drifted over on 3/16. We had rain/snow on 3/12. The long wall move is completed, but we have not gone sufficient distance to provide a map with this report.

Please contact us with questions or if you need additional information. Thanks, Vicky

From: Vicky Miller

Sent: Monday, March 9, 2015 7:27 AM

To: 'Steve Christensen (stevechristensen@utah.gov)'; 'Amanda Daniels (amandadaniels@utah.gov)'; 'Hamilton, Rob -FS (rhamilton@fs.fed.us)'; 'OGMCOAL OGMCOAL (OGMCOAL@utah.gov)'

Cc: Wyatt Shakespear; John Byars; Vicky Miller

Subject: South Fork of Quitchupah Monitoring

Access was attempted on February 23, 27, 28th and March 2 with no success in reaching the South Fork of Quitchupah due to snow, mud and heavy winds causing drifting. On March 3, snowmobiles were acquired and the site was reached and photos taken upstream and downstream of the access road, the stream channel was not visible. Snow observed on the third was estimated at 18 - 30 inches in the area of South Fork. Additional rock fall had occurred since the area was last visited on Dec. 17th. The ponds were snow covered, but assumed to be dry. A snow storm moved into the area on the third which forced the personnel checking the site to move off the mountain.

We completed mining the panel on 3/2/15 and are currently in the process of moving the long wall. Map has been attached.

Please contact us with questions or if you need additional information. Thanks, Vicky

From: Vicky Miller

Sent: Monday, February 23, 2015 7:25 AM

To: 'Steve Christensen (stevechristensen@utah.gov<mailto:stevechristensen@utah.gov>); 'Amanda Daniels (amandadaniels@utah.gov<mailto:amandadaniels@utah.gov>); 'Hamilton, Rob -FS (rhamilton@fs.fed.us<mailto:rhamilton@fs.fed.us>); 'OGMCOAL OGMCOAL (OGMCOAL@utah.gov<mailto:OGMCOAL@utah.gov>)'

Cc: Wyatt Shakespear; John Byars; Vicky Miller

Subject: FW: South Fork of Quitchupah Monitoring

We were still unable to access the South Fork of Quitchupah during the past two weeks (Feb. 9, 12, 16, 20). Attached are two photos, the one is taken at the lowest elevation of the access road to South Fork, the second is of the four-wheeler trail access. Our issues are still mud and drifts on the roads and trails. There is snow on the ground this morning (February 23) and if it stays cold and the ground freezes we may be able to access the site by road in the next two weeks. A map showing the location of mining is attached. Please contact us with questions or if you need additional information. Thanks, Vicky

From: Vicky Miller

Sent: Monday, February 9, 2015 9:04 AM

To: 'Steve Christensen (stevechristensen@utah.gov<mailto:stevechristensen@utah.gov>); 'Amanda Daniels

(amandadaniels@utah.gov<<mailto:amandadaniels@utah.gov>>); 'Hamilton, Rob -FS
(rhamilton@fs.fed.us<<mailto:rhamilton@fs.fed.us>>); 'OGMCOAL OGMCOAL
(OGMCOAL@utah.gov<<mailto:OGMCOAL@utah.gov>>)'
Cc: Wyatt Shakespear; John Byars; Vicky Miller
Subject: FW: South Fork of Quitchupah Monitoring

Attached is the map showing the location of mining. We were unable to access the South Fork of Quitchupah during the past two weeks (Jan 27, 29, Feb 3, 5) due to snow drifts and mud, we have attached photos of the access road near Accord Lakes. Due to the warm weather last week and the expected warm weather this week, we may be successful in reaching the site towards the end of the week. If you have questions or need additional information please contact us. Thanks, Vicky



DSC00236.jpg
7729K