



OGMCOAL DNR &lt;ogmcoal@utah.gov&gt;

---

## Quitcupah Monitoring November 30 thru December 16

1 message

---

**Vicky Miller** <vmiller@bowieresources.com>

Thu, Dec 17, 2015 at 8:23 AM

To: Steve Christensen &lt;stevechristensen@utah.gov&gt;, Amanda Daniels &lt;amandadaniels@utah.gov&gt;, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" &lt;rhamilton@fs.fed.us&gt;

Cc: OGMCOAL DNR &lt;ogmcoal@utah.gov&gt;, Wyatt Shakespear &lt;WShakespear@bowieresources.onmicrosoft.com&gt;, Jacob Smith &lt;jsmith@bowieresources.com&gt;



Please find attached a drawing showing the location of mining on December 16, 2015.

There was no access to the site on several days ( 30<sup>th</sup>, 14<sup>th</sup>, 15<sup>th</sup>) during the period due to drifted snow. On December 2, 4, 7, 8 we visited the area but were unable to see the flow at South Fork due to ice and drifted snow, all three ponds were dry. Spring flow was observed on Dec. 12, the springs appeared to be flowing at their normal rate. Wind has been excessive during this period of monitoring. It has snowed for some period of time since the 9<sup>th</sup> of December at the mine site, making us suspect that it has snowed at South Fork as well.

Please contact us for clarification or with questions. Regards, Vicky

**Mining December 16 2015.pdf**

216K



Trent Brown 3/30/2015 10:03 AM



**Canyon Fuel Company, LLC**  
**SUFCO Mine**  
 597 South SR 24 - Salina, UT 84654  
 (435) 286-4880 Phone  
 (435) 286-4499 Fax

WEST LEASE		
LONGWALL MINING SECTIONS		
SCALE: 1" = 1,000'	DATE: 3/30/2015	DRAWN BY: T.R.B.
ENGINEER:	CHECKED BY:	PROJ: ####
FILE NAME: H:\DRAWINGS\LONGWALL\WESTLEASE\LONGWALL_PANELS.dwg		

SHEET NO.  
1