



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitchupah

Vicky Miller <vmiller@bowieresources.com>

Mon, Jun 6, 2016 at 7:41 AM

To: Amanda Daniels <amandadaniels@utah.gov>, Steve Christensen <stevechristensen@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>



Cc: Wyatt Shakespear <WShakespear@bowieresources.onmicrosoft.com>, Vicky Miller <vmiller@bowieresources.com>, OGMCOAL DNR <ogmcoal@utah.gov>

The South Fork was visited on May 17, 20, 26 and 27, flow was 60 -65 gpm on the 17th, due to precipitation on the remaining days the flow ranged from 70 to 80 gpm. Due to the precipitation hiking into the canyon was unsafe, but water was observed to be flowing in the canyon on the first three visits. On the 27th water was observed to be flowing above and below the area of the rock fall at a similar rate. The area is greening up due to the warmer temperatures. One of the ponds had water in the bottom, the other two were dry. Springs west of the culvert were observed to be flowing at a rate similar to previous observations. A map showing the location of mining is attached. If there are questions or you need additional information please contact us at this e-mail address or at [\(435\)286-4481](tel:4352864481). Thanks, Vicky



Bowie Resource Partners - Scan Image from Sufco Lunch Room.pdf

218K



Canyon Fuel Company, LLC
SUFCO Mine
 597 South SR 24 - Salina, UT 84654
 (435) 286-4880 Phone
 (435) 286-4499 Fax

WEST LEASE		
LONGWALL MINING SECTIONS		
SCALE: 1" = 1,000'	DATE: 3/30/2015	DRAWN BY: T.R.B.
ENGINEER:	CHECKED BY:	PROJ: ###
FILE NAME: H:\DRAWINGS\LONGWALL\WESTLEASE\LONGWALL_PANELS.dwg		

SHEET NO.
1