



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitchupah Monitoring

Vicky Miller <vmiller@bowieresources.com>

Thu, Oct 20, 2016 at 7:58 AM

To: Steve Christensen <stevechristensen@utah.gov>, OGMCOAL DNR <ogmcoal@utah.gov>

Cc: Bryant Bunnell <BBunnell@bowieresources.com>, Jacob Smith <jsmith@bowieresources.com>

The Forest Service diversion has been redirected to take the flow to Skumtumpah Reservoir instead of allowing it to flow down South Fork. The springs in South Fork are still flowing and there is water in the immediate area of the springs. There continues to be flow in the channel to the confluence below the rock fall and Wedge and Amanda springs. There was still water flowing at the road crossing on October 6th, however by Oct 11th there was no flow. The ponds continue to be dry. We continue to monitor subsidence activity in the canyon. Please contact us with questions or concerns. Regards, Vicky



Presentation Oct 16 16.pptx

1055K





