



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork Quitchupah Monitoring

1 message

Bryant Bunnell <BBunnell@bowieresources.com>

Mon, Nov 14, 2016 at 1:02 PM

To: Vicky Miller <vmiller@bowieresources.com>, Steve Christensen <stevechristensen@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>

Cc: OGMCOAL DNR <ogmcoal@utah.gov>, Jacob Smith <jsmith@bowieresources.com>

South Fork Monitoring was completed on November 2, 4, 10 and 11th. Ponds continued to be dry as did the stream channel above and below the road crossing. Some water was observed just below the rock fall which was from discharge at Amanda and Wedge springs. A trickle of water entered from the South Fork at it's confluence with the North Fork of Quitchupah. The springs above the road crossing are discharging at their normal rates. On the 10th and 11th there was no visible running water anywhere in the South Fork of Quitchupah.

Please call if you need clarification or have any questions.

Thanks,

Vicky Miller

3 attachments



SF U.JPG
235K



DSC00208.JPG
7931K

DSC02813.JPG



8014K