



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitchupah Monitoring

Vicky Miller <vmiller@bowieresources.com>

Wed, Dec 28, 2016 at 12:04 PM

To: Steve Christensen <stevechristensen@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>, "Ogmcoal@utah.gov" <Ogmcoal@utah.gov>

Cc: Bryant Bunnell <BBunnell@bowieresources.com>, Jacob Smith <jsmith@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>

An attempt was made on December 12, 14, and 21 to access the site. As with previous weeks access was prevented by a combination of snow, ice and muddy conditions beneath the snow/ice. Snow was received in the area of the mine and South Fork on the 11, 13, 15, 16, 17, 18, 22, 24 and 25th of December. Snow fall was measured at 28 inches from the 11th thru the 25th. No access was assumed from the 22 thru the 25th, with 16" of snow accumulating at the mine site during those three days. Temperatures at the mine site average 33 degrees Fahrenheit during the day and 14 degrees at 5 pm. Single digit temperature were measured at 5 pm from the 16th thru the 25th.at the mine site. If you need additional information, please contact us at this e-mail address or at [\(435\)286-4481](tel:4352864481). Regards, Vicky