



OGMCOAL DNR &lt;ogmcoal@utah.gov&gt;

---

## South Fork of Quitchupah Monitoring

1 message

**Vicky Miller** <vmiller@bowieresources.com>

Mon, Feb 27, 2017 at 8:37 AM

To: Steve Christensen &lt;stevechristensen@utah.gov&gt;, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" &lt;rhamilton@fs.fed.us&gt;, "Ogmcoal@utah.gov" &lt;Ogmcoal@utah.gov&gt;

Cc: Jacob Smith &lt;jsmith@bowieresources.com&gt;, Bryant Bunnell &lt;BBunnell@bowieresources.com&gt;, Vicky Miller &lt;vmiller@bowieresources.com&gt;

The South Fork area has been receiving additional snow (17, 81, 19, 23), therefore the site continues to be inaccessible. Snow is expected today. Access was attempted on February 14, 15, 17, 21 and 24. Photos have been included for the 14, 15, 17 and 21. Questions can be directed to this e-mail address or to (435) 286-4481. Regards, Vicky

---

**From:** Vicky Miller**Sent:** Monday, February 13, 2017 6:46 AM**To:** Steve Christensen <stevechristensen@utah.gov>; 'Hamilton, Rob -FS (rhamilton@fs.fed.us)' <rhamilton@fs.fed.us>; Ogmcoal@utah.gov**Cc:** Jacob Smith <jsmith@bowieresources.com>; Bryant Bunnell <BBunnell@bowieresources.com>; Vicky Miller <vmiller@bowieresources.com>**Subject:** South Fork of Quitchupah Monitoring

The area of South Fork continues to be inaccessible. Although there has been some warmer days in the past weeks, we have still been receiving precipitation. Access was attempted on February 9, 7, 3, January 30, 26 and 23<sup>rd</sup>.

Photos have been included for the 23<sup>rd</sup> and 30<sup>th</sup> of January. Should you need additional information or have questions we can be contacted at this e-mail address or by phone (435)286-4481. Vicky

---

### 4 attachments



**P2140003.JPG**  
3240K

**P2150007.JPG**  
3274K



**20170217\_071700.jpg**  
4730K



**DSC00302.JPG**  
8045K