



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork Quitchupah Monitoring

1 message

Vicky Miller <vmiller@bowieresources.com>

Tue, Oct 3, 2017 at 7:48 AM

To: Steve Christensen <stevechristensen@utah.gov>, Arati Umarvadia <aumarvadia@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>

Cc: Jacob Smith <jsmith@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>, OGMCOAL DNR <ogmcoal@utah.gov>

For the week of September 25, we were able to access one day (27th, photos) and Erik Petersen (30th) was able to access one day. Flow averaged 59 gpm and could be seen and heard the length of South Fork from the road crossing to the confluence with the North Fork. Heavy rains fell on Monday and Tuesday of this week. Ponds in the area continued to have water in them. We will be discontinuing monitoring within the next few weeks as permitted. If you have questions please contact us at this e-mail address or at the number below. Thanks, Vicky

*Vicky Miller**Environmental Engineer**Sufco Mine**Office – 435 286-4481*

3 attachments

**P9270009.JPG**

3177K

P9270002.JPG

3312K



P9270006.JPG
3429K