

0005



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

DRZ
Jch

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: August 27, 1992
1:30 P. M. - 2:30 P. M.

Permittee and/or Operator's Name: Summit Minerals, Inc.
Business Address: 221 W. 2100 S., Salt Lake City, UT 84115
Phone: (801) 486-1861
Mine Name: Summit #1 Permit Number: INA/043/001
Type of Mining Activity: Underground X Surface Other
County: Summit Company Official(s): None Present
State Officials(s): Randy Harden
Federal Official(s): None
Partial: X Complete Date of last Inspection: 07/21/92
Weather Conditions: Clear, warm
Acreage: Permitted 0 Disturbed 16 Regraded 0
Seeded 0 Bonded 16 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	(X)	()	(X)
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION: 08/27/92

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

The access gate to the mine site was closed and posted. There was no sign of any activity at the site. Essentially all conditions at the site are the same as reported during previous inspections. No new disturbances have occurred since the last inspection.

1. PERMITS

Bond for the permit is under forfeiture by the Division. Conversion of the real property held as collateral for the bond has not yet sold and no fund are currently available to conduct reclamation of the site.

Photographs of the site were taken at the time of the inspection to document the current condition of the mine facilities.


Courtesy copy of this report should be sent to:

Keith H. Bates Investment Company
940 Donner Way
Salt Lake City, Utah 84104

Copy of this Report:

Mailed to: Brian Smith(OSM); Bates Inv. Co.

Given to: Daron Haddock, DOGM; Joe Helfrich, DOGM

Inspector's Signature & Number:  #13

Date: September 18, 1992