

0009

Document Information Form

Mine Number: C/043/008

File Name: Incoming

To: DOGM

From:

Person N/A

Company UTAH COAL + ENERGY Co.

Date Sent: N/A

Explanation:

MINE SITE EVALUATION
INSPECTION REPORT

cc:

File in: C/043/008 1984, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

Row D

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a Y Y M M	1b Batch	1c Report
---------------	-------------	--------------

2. Name of Permittee
UTAH COAL & ENERGY CO

3. Street Address
5511 SOUTH 4385 WEST

4. City KEARNS 5. State UT

6. Zip Code 84118 7. Area Code 801 8. Telephone Number 298-5901

9. MSHA Number

10. Date of Inspection (Y M M D D)
840117

11. State Permit Number
INA 043 001

12. Name of Mine
BLACKHAWK

13. County Code 043 14. State Code UT 15. Strata 16. State Area Office 01

17. OSM Field Office No.
02

18. OSM Area Office No.

19. OSM Sample No.

20. Type of Inspection (Code)
TDF

21. Joint Inspection
Yes No

22. Inspector's ID No.
031

23. Status

- A Type of Permit
- B Mine Status (Code)
- C 20 Type of Facility (Code)
- D Number of Permitted Acres
- E 00015.0 Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

- A Steep Slope
- B Mountain Top Removal
- C Prime Farmlands
- D Alluvial Valley Floors
- E Anthracite
- F Federal Lands
- G Indian Lands
- H Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

- A Distance Prohibitions
- B Mining Within Permit Boundaries
- C Signs and Markers
- D Sediment Control Measures
- E Design and Certification Requirements—Sediment Control
- F Effluent Limits
- G Surface Water Monitoring
- H Ground Water Monitoring
- I Blasting Procedures
- J Haul/Access Road Design and Maintenance
- K Refuse Impoundments
- L Other: Specify _____

Standards That Assure Reclamation Quality and Timeliness

- M Topsoil Handling
- N Backfilling and Grading
- O Following Reclamation Schedule
- P Revegetation Requirements
- Q Disposal of Excess Spoil
- R Handling of Acid or Toxic Materials
- S Highwall Elimination
- T
- U
- V
- W

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0009 Date N/A
In C 043/003, 7784, Incoming

For additional information

Row 1

United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report

For Office Use Only

1a Y Y M M	1b Batch	1c Report
---------------	-------------	--------------

2. Name of Permittee UTAH COAL & ENERGY CO				9. MSHA Number - - - - -				10. Date of Inspection (Y Y M M D D) 8 4 0 1 1 7							
3. Street Address 5511 SOUTH 4385 WEST								11. State Permit Number INA 043 001							
4. City KEARNS				5. State UT				12. Name of Mine BLACKHAWK							
6. Zip Code 84118		7. Area Code 801		8. Telephone Number 298-5901				13. County Code 043		14. State Code UT		15. Strata		16. State Area Office 01	

17. OSM Field Office No. 02	18. OSM Area Office No. 	19. OSM Sample No. 	20. Type of Inspection (Code) TDF	21. Joint Inspection Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	22. Inspector's ID No. 031
--------------------------------	-----------------------------	------------------------	--------------------------------------	---	-------------------------------

23. Status			24. Type of Activity (check applicable boxes).		
A <input type="checkbox"/>	Type of Permit		A <input type="checkbox"/>	Steep Slope	
B <input checked="" type="checkbox"/>	Mine Status (Code)		B <input type="checkbox"/>	Mountain Top Removal	
C <input checked="" type="checkbox"/>	Type of Facility (Code)		C <input type="checkbox"/>	Prime Farmlands	
D <input type="checkbox"/>	Number of Permitted Acres		D <input type="checkbox"/>	Alluvial Valley Floors	
E <input checked="" type="checkbox"/>	Number of Disturbed Acres		E <input type="checkbox"/>	Anthracite	
			F <input type="checkbox"/>	Federal Lands	
			G <input type="checkbox"/>	Indian Lands	
			H <input type="checkbox"/>	Other	

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

<p>Standards That Limit the Effects to the Permit Area</p> <p>A <input type="checkbox"/> Distance Prohibitions</p> <p>B <input type="checkbox"/> Mining Within Permit Boundaries</p> <p>C <input type="checkbox"/> Signs and Markers</p> <p>D <input type="checkbox"/> Sediment Control Measures</p> <p>E <input type="checkbox"/> Design and Certification Requirements—Sediment Control</p> <p>F <input type="checkbox"/> Effluent Limits</p> <p>G <input type="checkbox"/> Surface Water Monitoring</p> <p>H <input type="checkbox"/> Ground Water Monitoring</p> <p>I <input type="checkbox"/> Blasting Procedures</p> <p>J <input type="checkbox"/> Haul/Access Road Design and Maintenance</p> <p>K <input type="checkbox"/> Refuse Impoundments</p> <p>L <input type="checkbox"/> Other: Specify _____</p>	<p>Standards That Assure Reclamation Quality and Timeliness</p> <p>M <input type="checkbox"/> Topsoil Handling</p> <p>N <input type="checkbox"/> Backfilling and Grading</p> <p>O <input type="checkbox"/> Following Reclamation Schedule</p> <p>P <input type="checkbox"/> Revegetation Requirements</p> <p>Q <input type="checkbox"/> Disposal of Excess Spoil</p> <p>R <input type="checkbox"/> Handling of Acid or Toxic Materials</p> <p>S <input type="checkbox"/> Highwall Elimination</p> <p>T <input type="checkbox"/> Downslope Spoil Disposal</p> <p>U <input type="checkbox"/> Post Mining Land Use</p> <p>V <input type="checkbox"/> Cessation of Operations: Temporary</p> <p>W <input type="checkbox"/> Other _____</p>
--	---

**United States Department of the Interior
Office of Surface Mining
Mine Site Evaluation Inspection Report**

26. State Permit Number

IWA 043 001

27. Date of Inspection
(Y M M D D)

8 4 0 1 1 7

28. Yes No Do mining and reclamation activities on the site comply with the plans in the permit?
If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a. 00 Number of Completes

29b. 02 Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a. 03 Number of Completes

30b. 00 Number of Partials

31. Has inspection frequency been met?

31a. Yes No Completes

31b. Yes No Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Authorizations to Operate
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Signs and Markers
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Backfilling and Grading
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Highwall Elimination
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Rills and Gullies
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Improper Fills
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Topsoil Handling
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sediment Ponds
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Effluent Limits
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Water Monitoring
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Buffer Zones
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Roads
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Dams
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Blasting
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Revegetation
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Spoil on the Downslope
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Mining Without Permit
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exceeding Permit Limits
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Distance Prohibitions
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Toxic Materials
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Other Violations

33. Name of Authorized Representative (print or type)

FRANK ATENCIO

Signature of Authorized Representative

Frank Atencio

Date

Jan. 26, 1984

00 0

Signature of Reviewing Official

Date

Jeffrey C. ...

1/31/84

02 0

02 0

01 0

MINESITE EVALUATION INSPECTION REPORT NARRATIVE

UTAH COAL AND ENERGY COMPANY
5511 South 4385 West
Kearns, UT 84118

BLACKHAWK MINE

Inspection Date: January 17, 1984; INA 043/001

Inspector: Frank Atencio, #031

This inspection was conducted as a follow up to Ten-Day Notice (TDN) 83-2-31-2. The TDN was issued due to surface area drainage which was leaving the permit area untreated. A protective berm which should have been built to prevent this was non-existent at the time of the initial inspection.

No enforcement action was taken as a result of this follow-up inspection due to ground conditions. The snow cover on the mine area was from two to three feet in depth. It was difficult to determine with any degree of certainty if any corrective action had been attempted. Please note this is the reason why all of the performance standards (codes) in item 25 of the minesite evaluation inspection report were left blank.

This mine will need to be inspected when the snow begins to melt. In the meantime, the OSM inspector is attempting to obtain some background information on this mine operation. A check is being made to determine the production dates for the Blackhawk Mine and to establish if Utah Coal and Energy Company is still incorporated within the State of Utah. The Utah Division of Oil, Gas and Mining (DOGGM) has not taken direct action on this TDN since an interim permit was never issued for this mine. (Note: item 23A left blank.) DOGGM has since referred this matter to the State Attorney General's Office for advice. OSM believes that the non-issuance of a notice of violation by DOGGM in response to this TDN is inappropriate. OSM will continue to look into the circumstances surrounding this TDN until it is appropriately resolved.