

0012



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

February 14, 1989

HAND DELIVERED - FEBRUARY 16, 1989

Mr. Jack Blonquist  
Summit Coal Company  
Boyer Mine  
P. O. Box 646  
Coalville, Utah 84017


Dear Mr. Blonquist:

Re: Compliance Schedules for the Boyer Mine, Summit Coal Company,  
ACT/043/008, Folder #2, Summit County, Utah

Enclosed you will find a revised list of the outstanding violations with their deadline dates in conjunction with a scheduled compliance workload.

If you have any questions or comments, please feel free to call Harold Sandbeck, Joe Helfrich or myself.

Sincerely,

  
Susan C. Linner  
Reclamation Biologist/  
Permit Supervisor

cl  
cc: J. Helfrich  
H. Sandbeck  
BT45/169-170

SCHEDULED COMPLIANCE WORKLOAD

Inspection and Enforcement Issues

<u>ISSUES</u>	<u>DEADLINE</u>
1. Violation N88-27-5-1 was issued on September 23, 1988 for failure to abide by permit conditions regarding temporary storage of underground waste.	1. C88-27-2-1 was issued on December 23, 1988. NOV still outstanding.
2. C88-27-1 was issued on December 23, 1988 for failure to abate N88-27-5-1.	2. CO accrued a fine of \$22,500.00
3. Construct a permanent UD-1 energy dissipator. See field amendment ACT/043/008-88E. (3rd Modification)	3. May 15, 1989.
4. Reclaim the following areas: -UD-1 Buffer zone and install fence. -Mine fire disturbance area. -UD-1 culvert after installation. -Powder Magazine area. -Wildlife fence line disturbance.	4. N88-27-7-4, 3 of 4 was issued on December 2, 1988. June 30, 1989 Deadline
5. Failed to conduct water monitor per approved plan.	5. N89-27-1-2, 2 of 2 Terminated same day February 16, 1989.
6. Compliance with UMC performance standards.	6. On-going.

Page 3  
Mr. Jack Blonquist  
ACT/043/008  
February 14, 1989

PERMITTING ISSUES

<u>ISSUES</u>	<u>DEADLINE</u>
1. Operator must construct wildlife fence per approved plan.	1. N88-27-7-4, 2 of 4 was issued on December 2, 1988. June 30, 1989 Deadline
2. Operator must collect water samples in accordance with approved permit.	2. On-going.
3. After UD-1 culvert installation, operator must submit eight copies of revised as-built maps (all applicable Plates), revised applicable narrative discussing UD-1 drainage, and energy dissapator design for culvert outlet. Refer to field amendment number ACT/043/008-88E (3rd Modifications).	3. N89-27-1-2, 1 of 2 issued. Deadline May 16, 1989 (90th day).
4. Operator must provide a Class I Haul Road Certification. Operator must provide a pond certification.	4. N88-27-7-4, 1 of 4 was issued on December 2, 1988. March 2, 1989 deadline (90th day).
5. Operator must address and comply with the May 15, 1987 stipulations document.	5. See Division letter dated January 13, 1989. No further action until CO is resolved.
6. Operator must address issues in the Division's September 30, 1988 Conditional Approval package.	6. N88-28-8-1, was issued on December 16, 1988. March 16, 1989 Deadline (90th day).

Page 4  
Mr. Jack Blonquist  
ACT/043/008  
February 14, 1989

PERMITTING ISSUE

ISSUES

DEADLINE

- |                                                                                                                                                     |                                       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|
| 7. Conduct field measurements of the vegetation reference areas prior to July 10, 1989 and submit a final approval report prior to August 15, 1989. | 7. July 10, 1989 and August 15, 1989. |
| 8. Compliance with all other requirements of the approved permit.                                                                                   | 8. On-going.                          |

BT45/170-172