

0010

Document Information Form

Mine Number: C/043/008

File Name: Outgoing

To: DOGM

From:

Person N/A

Company SUMMIT COUNTY BEE

Date Sent: MARCH 07, 2003

Explanation:

TRANSACTION REPORT

cc:

File in: C/043/008, 2003, Outgoing

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

TRANSACTION REPORT

P. 01

MAR-07-2003 FRI 12:17 PM

FOR: OIL, GAS & MINING

801 359 3940

DATE	START	RECEIVER	TX TIME	PAGES	TYPE	NOTE	M#	DP
MAR-07	12:12 PM	14353365501	43"	1	SEND	COM. E-6	447	
	12:16 PM		1' 16"	2	SEND	OK	447	
TOTAL :						1M 59S	PAGES:	3



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
 PO Box 145801
 Salt Lake City, Utah 84114-5801
 (801) 538-5340 telephone
 (801) 359-3940 fax
 (801) 538-7223 TTY
 www.nr.utah.gov

Michael O. Leavitt
 Governor

Robert L. Morgan
 Executive Director

Lowell P. Braxton
 Division Director

March 7, 2003

FACSIMILE - (435) 336-5501
 E-mail - laurie@wasatchwave.com

Summit County Bee
 17 South Main
 Coalville, Utah 84017

Gentlemen:

Re: Public Notice, Boyer Mine, C/043/008

Attached is a Public Notice from the Division of Oil, Gas and Mining, Department of Natural Resources, State of Utah.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0010 3/7/03
 In C1043/008, 2003, Outgoing
 For additional information

PUBLIC NOTICE

Boyer Mine

Boyer Mine
Summit Coal Company
C/043/008

The reclamation bond for this mine was forfeited on October 20, 1995 and the mine was reclaimed as of November 20, 1997. Since the Boyer Mine is considered an abandoned site, the Division of Oil, Gas and Mining proposes in lieu of the inspection frequency established in R645-400-130, that inspections be set at a frequency commensurate with the public health and safety and environmental considerations present, but in no case shall the inspection frequency be set at less than one complete inspection per calendar year. This site was last inspected on January 22, 2003, and no threats to public or the environment were noted.

Boyer Mine is located on:

Fee Land

T3N R6E SLB&M, Utah

Sec 25: S1/2 S1/2,

Sec 36: North of the County Right of Way and a strip of land between the County highway and south of Chalk Creek running 800 feet west from the east side.

If you have any comments about the proposed reduction in the frequency of inspections for this mine, please send written comments within 30 days to:

Mary Ann Wright, Associate Director, Mining
Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
Salt Lake City, Utah 84114-5801