

October 2, 1984

TO: Memo to Coal File

FROM: Tom Munson *TM*

RE: Follow-up visit of Gabion Construction and Sediment Control Installation at the Truck Scale Loadout, Belina Complex, ACT/007/001, Folder #2, Carbon County, Utah

As a follow-up site inspection by Division Hydrologist John Whitehead and Tom Munson, the truck scale loadout area was looked at on September 14, 1984.

The following areas were looked at on this date.

1. Gabion installation in the roadside ditch adjacent to the truck scale.
2. Final grading and configuration of the area to achieve sediment control.

Area 1 was constructed properly and will have to be maintained regularly to achieve the desired result. When onsite, the ditch was full of coal fines and needed cleaning.

Area 2, was still raw unvegetated soil but nicely graded. There was some question as to the stability of this area due to its raw nature. A vegetative cover seems imperative to maintain sediment control and prevent erosion. The operator should vegetate this area as soon as possible.

re:

cc: Trevor Whiteside
Sandy Pruitt
95540-8