

NO. N 86-9-8-1

To the following Permittee or Operator:

Name Valley Camp of Utah, Inc.

Mine Belina Complex Surface Underground Other

County Carbon State Utah Telephone 801/637-8488-9413

Mailing Address Scofield Route Helper, Ut 84526

State Permit No. ACT/007/001

Ownership Category State Federal Fee Mixed

Date of inspection July 18, 19 86

Time of inspection 9:30 a.m. p.m. to ~~1:00~~ 4:35 a.m. p.m.

Operator Name (other than Permittee) as above

Mailing Address as above

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing July 18, 1986 Time of service/ mailing 9:35 a.m. p.m.

Permittee/operator representative Steve Tanner

Title Mine Engineer

Signature [Signature]

Division of Oil, Gas & Mining representative Holland Shepherd

Title Mining Field Specialist

Signature [Signature]

Identification Number # 9

SEE REVERSE SIDE

WHITE-DOGDM YELLOW-O5M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 86-9-8-1

Violation No. 1 of 1

Nature of violation

Failure to pass surface drainage through a treatment facility before leaving permit area.

Provisions of act, regulations or permit violated

- UMC 817.42 (a)(1)
- UCA 40-10-18 (i)
- UCA 40-10-18 (i) & (ii)

Portion of operation to which notice applies

1) The west embankment of the Belina haul road turn in has been used for the disposal of road material during winter snow maintenance. 2) Area has been disturbed during the installation of road drainage pipes.

In both situations above no sediment control measures were taken to control drainage from the disturbed areas.

Remedial action required (including any interim steps)

- 1) Install sediment control devices to protect stream from runoff coming from disturbed areas, 1 along base of pipe installation disturbance, 2 along diversion ditch where snow blown material was deposited.
- 2) Seed disturbed areas.
- 3) Clean diversion ditch from haul road to creek (or rerip rap).

Abatement time (including interim steps)

- #1) by 7-23-86
- 2) by 8-7-86
- 3) by 7-23-86