

arch 87



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

*gdk*  
*Jule*  
Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INPECTION REPORT

INSPECTION DATE & TIME: August 31, 1987  
1:30 p.m. to 3:30 p.m.

Permittee and/or Operators Name: Valley Camp of Utah  
Business Address: Scofield Route Helper, Utah 84526  
Mine Name: Belina Complex Permit Number: ACT/007/001  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon  
Company Official (s): Barry Barnum  
State Official(s): Holladn Shepherd  
Partial:  Complete:  Date of Last Inspection: July 15, 1987  
Weather Conditions: Sunny, clear and warm  
Acreage: Permitted 2837 Disturbed 79 Regraded 0 Seeded 0 Bonded 79  
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

|                                                                    | <u>YES</u> | <u>NO</u> | <u>N/A</u> | <u>COMMENTS</u> |
|--------------------------------------------------------------------|------------|-----------|------------|-----------------|
| 1. PERMITS                                                         | ( )        | ( )       | ( )        | ( )             |
| 2. SIGNS AND MARKERS                                               | ( X )      | ( )       | ( )        | ( X )           |
| 3. TOPSOIL                                                         | ( X )      | ( )       | ( )        | ( X )           |
| 4. HYDROLOGIC BALANCE:                                             |            |           |            |                 |
| a. STREAM CHANNEL DIVERSIONS                                       | ( X )      | ( )       | ( )        | ( )             |
| b. DIVERSIONS                                                      | ( )        | ( )       | ( )        | ( )             |
| c. SEDIMENT PONDS AND IMPOUNDMENTS                                 | ( X )      | ( )       | ( )        | ( )             |
| d. OTHER SEDIMENT CONTROL MEASURES                                 | ( )        | ( )       | ( )        | ( )             |
| e. SURFACE AND GROUNDWATER MONITORING                              | ( )        | ( )       | ( )        | ( )             |
| f. EFFLUENT LIMITATIONS                                            | ( )        | ( )       | ( )        | ( )             |
| 5. EXPLOSIVES                                                      | ( )        | ( )       | ( )        | ( )             |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL                         | ( )        | ( )       | ( )        | ( )             |
| 7. COAL PROCESSING WASTE                                           | ( )        | ( )       | ( )        | ( )             |
| 8. NONCOAL WASTE                                                   | ( )        | ( )       | ( )        | ( )             |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES   | ( )        | ( )       | ( )        | ( )             |
| 10. SLIDES AND OTHER DAMAGE                                        | ( )        | ( )       | ( )        | ( )             |
| 11. CONTEMPORANEOUS RECLAMATION                                    | ( )        | ( )       | ( )        | ( )             |
| 12. BACKFILLING AND GRADING                                        | ( )        | ( )       | ( )        | ( )             |
| 13. REVEGETATION                                                   | ( )        | ( )       | ( )        | ( )             |
| 14. SUBSIDENCE CONTROL                                             | ( )        | ( )       | ( )        | ( )             |
| 15. CESSATION OF OPERATIONS                                        | ( )        | ( )       | ( )        | ( )             |
| 16. ROADS                                                          |            |           |            |                 |
| a. CONSTRUCTION                                                    | ( )        | ( )       | ( )        | ( )             |
| b. DRAINAGE CONTROLS                                               | ( X )      | ( )       | ( )        | ( )             |
| c. SURFACING                                                       | ( X )      | ( )       | ( )        | ( X )           |
| d. MAINTENANCE                                                     | ( X )      | ( )       | ( )        | ( X )           |
| 17. OTHER TRANSPORTATION FACILITIES                                | ( )        | ( )       | ( )        | ( )             |
| 18. SUPPORT FACILITIES                                             |            |           |            |                 |
| UTILITY INSTALLATIONS <small>an equal opportunity employer</small> | ( )        | ( )       | ( )        | ( )             |

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION August 31, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

The operator needs to repaint perimeter markers and replace those that have fallen down around the site.

3. TOPSOIL:

The operator's Belina topsoil stockpile is stable; however, the operator needs to replace straw bales which help to protect the pile's north toe. No loss of soil material has occurred at this time.

16c.ROAD SURFACING:

The operator resurfaced the Belina haul road last month. The road has a fresh layer of oil from top to bottom of the canyon.

16d.ROAD MAINTENANCE:

The Belina haul road is currently well maintained. There is very little debris in the concrete lined ditch, and sediment control straw bales have been replaced where worn. Culverts and drop drains are clear, along the length of the road.

Copy of this Report:

Mailed to: Barry Barnum (Valley Camp), Brian Smith (OSM)

Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd #9 Date: Sept. 3, 1987