



NO. N87-9-14-1

notice of violation

To the following Permittee or Operator:

Name Valley Camp of Utah, Inc.

Mine Bellevue Complex Surface Underground Other

County Carbon State Utah Telephone 801/448-9413

Mailing Address Scofield Route Helper, UT 84526

State Permit No. ACT/007/001

Ownership Category State Federal Fee Mixed

Date of inspection 11-5-87, 19

Time of inspection 8:30 a.m. p.m. to 4:00 a.m. p.m.

Operator Name (other than Permittee) same as above

Mailing Address same as above

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., **Utah Code Annotated**, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 11-5-87 Time of service/ mailing 4:00 a.m. p.m.

Barry Barnum
Permittee/Operator representative

Environmental Coordinator
Title

Barry Barnum
Signature

Holland Shepard
Division of Oil, Gas & Mining representative

Reclamation Specialist #9
Title

Holland Shepard
Signature

Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

CRRP

POO 1 771 234



NOTICE OF VIOLATION NO. N87-9-14-1

Violation No. 1 of _____

Nature of violation

Failure to maintain road culverts in such a manner which prevents plugging, collapse or erosion at inlets and outlets.

Provisions of act, regulations or permit violated

UAC 87.153 (c) (1) (ii)

Portion of operation to which notice applies

1. 36" culvert, located at station 20+00 on the Belina haul road, requires outlet protection 2. culvert located on office ~~outlet~~ access road, one end crushed 3. 24" culvert located by oil shack, one end crushed 4. 24" culvert located by the loading bin is plugged and crushed on one end.

Remedial action required (including any interim steps)

1. Repair crushed culverts
2. clean out plugged inlets and outlets (and everything inbetween)
3. riprap outlet of 36" culvert appropriately

Abatement time (including interim steps)

all to be done by Nov. 30th 1987