

### Document Information Form

Mine Number: C007001

File Name: Internal

To: DOGM

**From:**

Person N/A

Company Valley Camp of Utah

Date Sent: N/A

**Explanation:**

Inspection Report

\_\_\_\_\_  
\_\_\_\_\_

cc:

File in: C/007, 001, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date N/A For additional information



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*John DR7*

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

PERMIT NO.: ACT/007/001

Inspection Date: December 17, 1990

Permittee and/or Operators Name: Valley Camp of Utah Inc.  
 Business Address: Scotfield Route  
 City: Helper State: Utah Zip: 84526  
 Mine Name: Belina  
 County: Carbon State: Utah  
 Type of Mining Activity: Underground  Surface  Other   
 Company Official (s): Steve Tanner  
 State Officials (s): Steve J. Demczak  
 Time of Inspection: 9:30 (X)a.m. ( )p.m. to 11:45 (X)a.m. ( )p.m.  
 Partial  Complete:  Date of Last Inspection: 11/30/90  
 Weather Conditions: Cold/Clear 18" snow on the ground  
 Acreage: Permitted 3136 Disturbed Regraded 79 Seeded            Bonded 79  
 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( X )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( X )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES	( )	( )	( )	( )
UTILITY INSTALLATIONS	( )	( )	( )	( )

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0001 Date N/A  
 In C/ 007, 001, Internal

For additional information



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

*John DR7*

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

PERMIT NO.: ACT/007/001

Inspection Date: December 17, 1990

Permittee and/or Operators Name: Valley Camp of Utah Inc.  
 Business Address: Scotfield Route  
 City: Helper State: Utah Zip: 84526  
 Mine Name: Belina  
 County: Carbon State: Utah  
 Type of Mining Activity: Underground  Surface  Other   
 Company Official (s): Steve Tanner  
 State Officials (s): Steve J. Demczak  
 Time of Inspection: 9:30  a.m.  p.m. to 11:45  a.m.  p.m.  
 Partial  Complete:  Date of Last Inspection: 11/30/90  
 Weather Conditions: Cold/Clear 18" snow on the ground  
 Acreage: Permitted 3136 Disturbed Regraded 79 Seeded            Bonded 79  
 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. SURFACE AND GROUNDWATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL PROCESSING WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS				
a. CONSTRUCTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. MAINTENANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/001

INSPECTION DATE December 17, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. Diversions:

All diversions were filled with snow. There were no signs of disturbance and low temperature prohibited the flow of water.

c. Sediment Ponds and Impoundments:

Sediment Pond #5 was discharging water which appeared to be clear. All other ponds were not discharging and were covered with 12" to 18" of snow.

16. ROADS:

b. Drainage controls:

Roads were scraped and salted by snow plows. No drainage was taking place due to cold weather conditions.

Copy of report:

Mailed to: Steve Tanner

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39 Date: 12/21/90

*Stephen J. Demczak*