

Document Information Form

Mine Number: C007001

File Name: Internal

To: DOGM

From:

Person N/A

Company Valley Camp of Utah

Date Sent: N/A

Explanation:

Inspection Report

cc:

File in: C/007, 001, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date N/A For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 29, 1990
10:00 am to 3:00 pm

Permittee and/or Operators Name: Valley Camp of Utah, Inc.
Business Address: Scofield Route Helper, Utah 84526
Mine Name: Belina Complex Permit Number: ACT/007/001
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Ed Foust
State Official(s): David Darby
Partial: Complete: Date of Last Inspection: February 13, 1990
Weather Conditions: Clear, Moderate Temperature
Acreage: Permitted 3136 Disturbed 79 Regraded Seeded Bonded 79
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUND WATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No. 0024 Date N/A
In C/ 007, 001, Internal
For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gh

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 29, 1990
10:00 am to 3:00 pm

Permittee and/or Operators Name: Valley Camp of Utah, Inc.
Business Address: Scofield Route Helper, Utah 84526
Mine Name: Belina Complex Permit Number: ACT/007/001
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Ed Foust
State Official(s): David Darby
Partial: Complete: Date of Last Inspection: February 13, 1990
Weather Conditions: Clear, Moderate Temperature
Acreage: Permitted 3136 Disturbed 79 Regraded Seeded Bonded 79
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUND WATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION March 29, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permitting

The Division is currently reviewing Valley Camps Permit Application Package for the 5-year permit evaluation.

4d. Hydrologic Balance-Other Sediment Control Measures

All five sedimentation ponds on Valley Camp's permit area were checked for integrity and operation. Sedimentation Ponds 001 and 002 some water, but were far from discharging. Pond 003 was dry.

Pond 004 discharges into Whiskey Creek. It was discharging approximately 50 gallons per minute on the day of the inspection. No sample was taken because of the visual clarity of the discharging water.

Pond 005, the mine discharge pond, was not discharging.

Copy of this report:

Mailed to: Ed Foust (Valley Camp), Brian Smith (OSM), PFO
Sent to: Joe Helfrich, Daron Haddock (DOGM)

Inspectors Signature and Number: David W. Darby #18 Date: Apr. 6, 1990