

Document Information Form

Mine Number: C1001/001

File Name: Internal

To: DOGM

From:

Person N/A

Company Valley Camp

Date Sent: N/A

Explanation:

Inspection Report

cc:

File in: C1001/001, 1991, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

jd
2077

INSPECTION REPORT

INSPECTION DATE & TIME: November 8, 1991
8:35 A.M. to 12:00 P. M.

Permittee and/or Operator's Name: Valley Camp
Business Address: Scofield Route, Helper, UT 84526
Mine Name: Belina Complex Permit Number: ACT/007/001 County: Carbon
Type of Mining Activity: Underground Surface Other
Company Official(s): Kit Pappas, Steve Tanner State Officials(s): Paul Baker Federal Official(s): None
Partial: Complete: Date of last Inspection: October 29, 1991
Weather Conditions: Clear, 40's
Acreage: Permitted- 3136 Disturbed- 79 Regraded- Seeded- Bonded- 79
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	(X)	()	()	(X)
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES				
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS				

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0001 Date
In C/007/001, 1991, Internal
For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

jd
2077

INSPECTION REPORT

INSPECTION DATE & TIME: November 8, 1991
8:35 A.M. to 12:00 P. M.

Permittee and/or Operator's Name: Valley Camp
Business Address: Scofield Route, Helper, UT 84526
Mine Name: Belina Complex Permit Number: ACT/007/001 County: Carbon
Type of Mining Activity: Underground Surface Other
Company Official(s): Kit Pappas, Steve Tanner State Officials(s): Paul Baker Federal Official(s): None
Partial: Complete: Date of last Inspection: October 29, 1991
Weather Conditions: Clear, 40's
Acreage: Permitted- 3136 Disturbed- 79 Regraded- Seeded- Bonded- 79
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. OTHER SEDIMENT CONTROL MEASURES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. SURFACE AND GROUNDWATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL PROCESSING WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS				
a. CONSTRUCTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. MAINTENANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION: November 11, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

3. Topsoil

The substitute soil material at the Valcam Loadout is protected with berms and straw bales and does have some vegetation growing on it. The location is very narrow, however, right next to the railroad tracks, and additional vegetation would be helpful to control soil movement. Mr Tanner stated that this stockpile was seeded once but that all of the vegetation was eaten very quickly after emerging. It is too late to seed this year, but unless this material can be used, some attempt to vegetate this stockpile should be made next year.

4.b. Diversions

Culverts and diversion ditches were checked and found to be in good repair. Culvert C-36-12 had minor sediment accumulation at the inlet. Ditch D-38 was still functional but needed some redefinition. Both of these are in areas with a lot of activity and are maintained frequently.

5. Explosives


I checked the sites for temporary explosives storage as indicated on the map in the recent amendment. They were as shown on the map, and signs were posted indicating the presence of explosives.

Copy of this Report:

Mailed to: Steve Tanner (Valley Camp), Bernie Freeman (OSM)

Given to: Daron Haddock, Joe Helfrich (DOGM)

Inspector's Signature: _____



Paul B. Baker #41 Date: November 25, 1991