



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/007/001 Inspection Date: February 18, 1992
Permittee and/or Operators Name: Valley Camp of Utah
Business Address: Scofield Route City: Helper State: Utah Zip: 84526
Mine Name: Belina Complex County: Carbon State: Utah
Type of Mining Activity: Underground XX Surface Other
Company Officials: Steve Tanner State Officials: Stephen J. Demczak
Time of Inspection: 9:00 a.m. - 11:30 a.m. Partial X Complete:
Acreage: Permitted 3136 Disturbed 79 Regraded 0
Seeded 0 Bonded 79 Date of Last Inspection: January 8 - 9, 1992
Weather Conditions: 20's, 2' Snow Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. <u>PERMITS</u>	()	()	()	()
2. <u>SIGNS AND MARKERS</u>	(X)	()	()	(X)
3. <u>TOPSOIL</u>	()	()	()	()
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	()	()	()	()
b. <u>DIVERSIONS</u>	(X)	()	()	(X)
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	(X)	()	()	(X)
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	()	()	()	()
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	()	()	()	()
f. <u>EFFLUENT LIMITATIONS</u>	()	()	()	()
5. <u>EXPLOSIVES</u>	()	()	()	()
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	()	()	()	()
7. <u>COAL PROCESSING WASTE</u>	()	()	()	()
8. <u>NONCOAL WASTE</u>	(X)	()	()	()
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	()	()	()	()
10. <u>SLIDES AND OTHER DAMAGE</u>	()	()	()	()
11. <u>CONTEMPORANEOUS RECLAMATION</u>	()	()	()	()
12. <u>BACKFILLING AND GRADING</u>	()	()	()	()
13. <u>REVEGETATION</u>	()	()	()	()
14. <u>SUBSIDENCE CONTROL</u>	()	()	()	()
15. <u>CESSATION OF OPERATIONS</u>	()	()	()	()
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	()	()	()	()
b. <u>DRAINAGE CONTROLS</u>	()	()	()	()
c. <u>SURFACING</u>	()	()	()	()
d. <u>MAINTENANCE</u>	()	()	()	()
17. <u>OTHER TRANSPORTATION FACILITIES</u>	()	()	()	()
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	()	()	()	()
19. <u>AVS Check</u>	(X)	()	()	(X)

Permit No. ACT/007/001 Inspection Date February 18, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

The signs were inspected and all information was correct and contained the necessary information. They were also posted at the gates entering the properties.

4b. Diversions -

The diversion ditches along the haul road were being cleaned of snow by a road grader during the inspection. No diversions were flowing due to the cold temperature.

4c. Sediment Ponds and Impoundments -

The sediment ponds were snow covered and there were no signs of water flow in or out of them.

Copy of report:

Mailed to: Valley Camp of Utah

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Date: February 21, 1992

Inspector's Signature and Number: Stephen J. Demczak #39
Stephen J. Demczak