

0027
gjt



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/007/001 Inspection Date: July 16, 1992
 Permittee and/or Operators Name: Valley Camp of Utah
 Business Address: Scotfield Route City: Helper State: Utah Zip: 84526
 Mine Name: Belina Complex County: Carbon State: Utah
 Type of Mining Activity: Underground Surface Other
 Officials: Company: Ed Foust State: Stephen J. Demczak/Wayne Western
 Time of Inspection: 9:00 a.m. - 3:00 p.m. Partial Complete:
 Acreage: Permitted 3136 Disturbed 79 Regraded 0
 Seeded 0 Bonded 79 Date of Last Inspection: June 3, 1992
 Weather Conditions: 80's/Warm Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. PERMITS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. SURFACE AND GROUNDWATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. COAL PROCESSING WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS				
a. CONSTRUCTION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. MAINTENANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Permit No. ACT/007/001 Inspection Date July 16, 1992(Comments are Numbered to Correspond with Topics Listed Above)1. Permits -

- a. The quarterly pond inspections were February 28, 1992 and April 29, 1992 with no problems noted. The ponds have not discharged yet this year.
- b. Valley Camp have given notice to the division of cessation of operation as of June 25, 1992. Valley Camp is presently shipping coal in small quantities therefore, does not qualify for cessation. Valley Camp may commence operations one mining contracts are available.
- c. Valley Camp is insured by Home Indemnity and the policy has exceeded the required minimum coverage limits. The policy Number is 6LR989061 and it expires on 4-1-93.
- d. NPDES - no discharge has occurred this year. Permit will expire on August 31. 1997. (UT 0022985)
- e. Valley Camp is a Utah corporation which is owned by Quaker State Corporation.
- f. Water monitoring has been taken from April to June. All parameters have been taken.

4b. Diversions -

The straw bales in several area will require cleaning since the last storm. Sediment has built up behind them. No violation has taken place.

4c. Sediment Ponds and Impoundments -

The ponds were inspected and did contain water, but they were not discharging. There were no signs of erosion of inlet, outlet, or embankments. The pond at lower mine site by load out might be drained by the request of State Water Rights. Samples of water will be done if draining takes place.


Permit No. ACT/007/001 Inspection Date July 16, 1992<Comments are Numbered to Correspond with Topics Listed Above>8. Noncoal Waste -

All area at the mine site were clear of non coal waste. This will most likely be the case since mining operations have ceased.

19. AVS Check -

An AVS check has been taken at the mine site with no new changes.

Copy of report:

Mailed to: Valley Camp of UtahMailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: July 22, 1992Inspector's Signature and Number:  #39
Stephen J. Demczak