



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 DIVISION OF OIL, GAS AND MINING

[Handwritten initials]

Norman H. Bangertter
 Governor
 Dee C. Hansen
 Executive Director
 Dianne R. Nielson, Ph.D.
 Division Director

355 West North Temple
 3 Triad Center, Suite 350
 Salt Lake City, Utah 84180-1203
 801-538-5340

INSPECTION REPORT

Partial: XX Complete: Exploration
 Inspection Date/Time: February 17, 1993/09:00am-12:00pm
 Date of Last Inspection: January 28, 1993

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001
 Permittee and/or Operator's Name: Valley Camp of Utah
 Business Address: Scofield Route, Helper, UT 84526
 Type of Mining Activity: Underground XX Surface Prep. Plant Other
 Official(s): State: Stephen J. Demczak Company: Steve Tanner
 Federal Official(s): Weather Conditions: Snowing 48"
 Existing Acreage: Permitted-3136 Disturbed-79 Regraded- Seeded- Bonded-79
 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
 Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture
 Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[]	[]	[]	[]
2. SIGNS AND MARKERS	[XX]	[]	[XX]	[]
3. TOPSOIL	[]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[]	[XX]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[]	[]	[]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June)	[XX]	[]	[XX]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: February 17, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers

Identification signs were inspected for information and location. The signs were located where public roads has access to areas of surface operations and facilities on the permit area.

4a. Diversions

Diversions were covered with 41 inches of snow. Snow was not melting at the time of inspection.

4b. Sediment Ponds & Impoundments

The sediment ponds did contain water but were not discharging. The embankments were covered with approximately 41 inches of snow fall.

19. AVS Check

An AVS check has been taken at the mine site with no new changes in ownership and control.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Ed Foust

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: March 3, 1993

Inspector's Signature and Number: Stephen J. Demczak

Stephen J. Demczak

#39