

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: December 7, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The permit transfer from Valley Camp to White Oak Mining and Construction is still under review by the Division. Additional information is required from White Oak Mining for an AVS release and a reclamation bond in White Oak Mining and Construction. At this time, Valley Camp is holding the reclamation bond.

2. Signs & Markers -

The White Oak identification sign has been modified since last inspection. Additional information had been added to the sign; it now includes the address and phone number.

4a. Diversions -

The majority of the diversions were either snow covered or were iced over. It appears the water was flowing under the ice and snow.

4b. Sediment Ponds and Impoundments -

The sediment pond and filter pond was covered with snow at the time of inspection. All ponds were not discharging and no performance standards have been violated due to snow cover.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOG M)

Filed to: Price Field Office

Date: December 9, 1993

Inspector's Signature and Number:


Stephen J. Demczak

#39