



NO. N96-7-1-1

To the following Permittee or Operator:

Name White Oak Mining and Construction Co., Inc.

Mine White Oak Loadout Surface Underground Other

County Carbon State Utah Telephone (801) 448-9413

Mailing Address Scotfield Route Helper, UT 84526

State Permit No. ACT/007/001

Ownership Category State Federal Fee Mixed

Date of inspection March 28, 1996, 19__

Time of inspection 10:30 a.m. p.m. to 4:15 a.m. p.m.

Operator Name (other than Permittee) SAME

Mailing Address SAME

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., Utah Code Annotated, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that cessation of mining is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing March 28, 1996 Time of service/ mailing 4:00 a.m. p.m.

Steve Tanner
Permittee/Operator representative

Environmental Coordinator
Title

[Signature]
Signature

Ken Wyatt
Division of Oil, Gas & Mining representative

Reclamation Specialist III
Title

Ken Wyatt
Signature

#7
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 96-7-1-1

Violation No. 1 of 1

Nature of violation

Failure to maintain sediment control structures

Provisions of act, regulations or permit violated

R645-301-706-742, 220 et seq.

Portion of operation to which notice applies

Sediment pond 003A. Northwest corner of pond. at
White Oak Landcut. where animals or other conditions have
created piping through the embankment

Remedial action required (including any interim steps)

- A) Repair embankment to eliminate leak until weather conditions allow for permanent repair.
- B) Monitor repair for part A above until such time as conditions allow for permanent repair which will be when equipment can access the area.

Abatement time (including interim steps)

- A) Monday, April 1, 1996 by 5:00 pm
- B) Monitor until area becomes accessible by equipment